

## **Apeiron Firmware Release Notes**

### **Supported products**

**List of scanner product types supported by the firmware.**

- HD Apeiron/42

### **Version Changes**

#### **Changes in version 5.0.1 - 008**

- Sometimes error message 'No supported scanner was found' occurred when scanning through the USB3 interface

#### **Changes in version 5.0.1 - 007**

- HDA-76: The scanner will blink lamps and move table at startup
- HDA-77, HDA-91: Improved black adjustment
- HDA-81: Fix some cases of USB timeouts
- HDA-86, HDA-87: The motor now stops if transmission cable breaks
- HDA-80: Table movement could be slow in some cases
- HDA-95: Support for multi exposure
- HDA-99: Improved image quality (sampling times)
- HDA-100: Better error handling when scanning stops prematurely
- HDA-103: Sometimes the last lines in a scan could contain wrong data
- HDA-66: Scanner calibration could fail in some cases