

Scanner firmware release note

Installation

To install the firmware, please download and run the firmware executable from Contex support Website: <https://contex.com/technical-support/>

Supported products

List of scanner product types supported by the firmware.

- TA53D, SD One 36
- TB53D, SD One 24
- TL53D, SD One+ 36
- TM53D, SD One+ 24

Firmware version changes

Changes in 3.0.9-005 build 112234

- | |
|---|
| <ul style="list-style-type: none">• Support for new Nextimage 7 license system. |
|---|

Changes in 3.0.9-004 build 89603

Required software		WIDSystem version 5.1 or newer
37157	Fixed	Sleep mode for these scanners are limited to 1-60 minutes and it will not be possible to disable sleep mode.

Changes in 3.0.9-003 build 68701

Required software		WIDSystem version 5.1 or newer
31523	New	New scanner models introduced (+model)
30026	Fixed	Issue related to paper eject is fixed
31675	New	Blue light on CIS elements during boot

Changes in 3.0.9-002 build 61787

Required software		WIDSystem version 5.1 or newer
29693	New	Only allow scanner to power down (energy star) when in Idle

Changes in 3.0.9-001 build 59917

Required software		WIDSystem version 5.0 or newer
29190	New	Scanner name correction for first release of firmware for this type of scanner