#### Wide Format Scanning and Copying Software

At first start-up you are required to specify a Product Key. The Product Key is located on the distribution media or distributed as a printed or electronic document.

If uninstalling Nextimage, the WIDEsystem driver needs to be uninstalled separately.

#### **Contents**

Version Changes
Supported Operating Systems
Supported Scanners
Supported Printers

#### **Version Changes**

#### Changes in version 4.5.1

32307	New	Support for various scanners – see Supported Scanners.
32220	New	Support for HP DesignJet Z2600/Z5600 added.
32288	New	Improved auto size.
32946	New	Support for Canon PRO 1000/500/2000/4000/520/540/4000S/6000S/540S/560S added (network only).
32168	Fix	Unable to print to ColorWave 810/900/910.
32481	Fix	Unable to scan with TWAIN when trial period had expired.

31671	New	Support for new SD One+ scanner.
31665	New	Scan History feature allow reload of earlier scans for re-adjustments or reprinting.
30800	New	Clear Image option to remove the scanned image from screen after a specified period.
31667	New	Touch screen swipe support in panel and browser lists.
31739	New	Administrative protection of Scan History and Clear Image settings by specifying fixed values in the Nextimage.exe.admin.config file in the installation folder.
31735	Fix	Some decimal values were not saved in presets when not using period as decimal symbol in Windows.
31786	Fix	Message about low disk space could incorrectly be displayed.

31815	Fix	'First Time' configuration dialog was sometimes shown after an upgrade.
31814	Fix	Some configuration paths of the Cache File Location option were not accepted.

## Changes in version 4.4.3

31271	New	Support for EPSON SC-T3200D, SC-T3250, SC-T3250D, SC-T3270, SC-T3270D, SC-T5250D, SC-T5250D, SC-T5270D, SC-T7250, SC-T7250D, SC-T7270D.
31342	Fix	Missing texts under icons in image tool bar.
31390	Fix	For HP PageWide XL the Print Quality did not select the correct options.
31544	Fix	Auto White Point / Black Point gave wrong result when used in combination with sharpen.
31563	Fix	Unable to select scan resolution in Touch Mode at a specific panel width.
	Fix	Several updates to user interface, translations and help.

#### Changes in version 4.4.2

30931	New	Support for Epson Stylus Pro 7710, 7880, 7880C, 7890, 7900, 7910,
31218		9710, 9880, 9880C, 9890, 9900, 9910, 11880, 11880C and Epson
		SureColor SC-P6000, SC-P7000, SC-P8000, SC-P9000.

## Changes in version 4.4.1

30621	New	Support for HP PageWide XL 4000/4500/5000/8000.
30687	New	Support for Océ ColorWave 500/700/810/900/910.
		Support for Océ PlotWave 340/360/500.
30866	New	Support for HP Designjet T930/T1530/T2530.
30867	New	Support for HP Designjet T730/T830 MFP.
30669	New	Improved reaction time when cancelling a scan.
30696	New	Improved reaction time when starting a scan.
30799	New	Media control buttons to move original in SD One scanner.
30620	Fix	Black and white point did not work correctly when using Adaptive
		Threshold.
30639	Fix	Error message could appear during shut down of application.
30869	Fix	Switching Task could take very long time.
30822	Fix	Application crash when starting a scan while having extension-less files in
		the Windows Color folder.
30797	Fix	Missing support for legacy scanner HD5430.

30395	New	Support for Canon iPF830/840/850 and iPF831/841/851.
29872	Fix	When scanning an original smaller than a selected fixed size, only the size
		of the original was indicated in the viewer and subsequently saved to file.

30077	Fix	Multipage TIF could result in invalid files when re-saving or deleting the
30245		last scan.
30086	Fix	Using French on-screen keyboard (in Touch Screen mode) could result in
		the numeric on-screen keyboard not working.
30181	Fix	The Output file option 'If file exist' was sometimes automatically set to
		'Rename'.
30181	Fix	When inserting a counter field larger than 1 in the file name in batch mode,
		could cause wrong naming of files.
30295	Fix	The 'Delete Last Scan' function did not decrement file name counter field
		used while in batch mode.
		Several user interface corrections

#### Changes in version 4.3.2

the same filename.  29731 New 'Repro Edition Trial' option added for SD One scanners.  29986 New Improved reaction time between pressing 'Scan' button and start of scan.  30003 New Improved auto size detection on iFLEX scanner.  27534 Fix Gamma was sometimes changed to 5.0 when not using period as decimal separator.  28900 Fix For IQ Quattro scanners the 'Light Source' option was sometimes hidden.  29026 Fix Scanning 'B&W Threshold' or 'B&W Adaptive' via TWAIN sometimes caused error.  29039 Fix Image on screen was shown with the printer's color calibration when copying using Closed Loop Calibration (CLC).  29543 Fix Installation did not always ask for admin rights even though they are required.  29861 Fix For SD One scanners two scans were made if double clicking the 'Scan' button in the Share task.  29865 Fix For SD One scanners clicking the 'Save' button in the Share task while still transferring an image to the cloud resulted in an upload error.  29879 Fix Using the 'Descreening' resolution type on iFLEX together with auto size resulted in a large white area added to file.  29919 Fix Using 'Mirror' and 'Indexed Color' sometimes resulted in a vertical line in the middle of the scan.  29963 Fix Unified installation of Nextimage and the WIDEsystem driver did not ask for reboot when launched from USB key.  30161 Fix Several user interface corrections.	29628	New	'Delete Last Scan' button added in Output File panel to ease rescanning to
New Improved reaction time between pressing 'Scan' button and start of scan.  New Improved auto size detection on iFLEX scanner.  Gamma was sometimes changed to 5.0 when not using period as decimal separator.  Fix For IQ Quattro scanners the 'Light Source' option was sometimes hidden.  Scanning 'B&W Threshold' or 'B&W Adaptive' via TWAIN sometimes caused error.  Image on screen was shown with the printer's color calibration when copying using Closed Loop Calibration (CLC).  Fix Installation did not always ask for admin rights even though they are required.  Fix For SD One scanners two scans were made if double clicking the 'Scan' button in the Share task.  Fix For SD One scanners clicking the 'Save' button in the Share task while still transferring an image to the cloud resulted in an upload error.  Pix Using the 'Descreening' resolution type on iFLEX together with auto size resulted in a large white area added to file.  19919 Fix Using 'Mirror' and 'Indexed Color' sometimes resulted in a vertical line in the middle of the scan.  19963 Fix When printing to HP Designjet T7100 the active roll was used instead of the media selected.			the same filename.
South	29731	New	'Repro Edition Trial' option added for SD One scanners.
Fix Gamma was sometimes changed to 5.0 when not using period as decimal separator.  For IQ Quattro scanners the 'Light Source' option was sometimes hidden.  Scanning 'B&W Threshold' or 'B&W Adaptive' via TWAIN sometimes caused error.  Image on screen was shown with the printer's color calibration when copying using Closed Loop Calibration (CLC).  Installation did not always ask for admin rights even though they are required.  Fix For SD One scanners two scans were made if double clicking the 'Scan' button in the Share task.  Fix For SD One scanners clicking the 'Save' button in the Share task while still transferring an image to the cloud resulted in an upload error.  Using the 'Descreening' resolution type on iFLEX together with auto size resulted in a large white area added to file.  Using 'Mirror' and 'Indexed Color' sometimes resulted in a vertical line in the middle of the scan.  Unified installation of Nextimage and the WIDEsystem driver did not ask for reboot when launched from USB key.  When printing to HP Designjet T7100 the active roll was used instead of the media selected.	29986	New	Improved reaction time between pressing 'Scan' button and start of scan.
separator.  Fix For IQ Quattro scanners the 'Light Source' option was sometimes hidden.  Scanning 'B&W Threshold' or 'B&W Adaptive' via TWAIN sometimes caused error.  Image on screen was shown with the printer's color calibration when copying using Closed Loop Calibration (CLC).  Installation did not always ask for admin rights even though they are required.  Fix For SD One scanners two scans were made if double clicking the 'Scan' button in the Share task.  Fix For SD One scanners clicking the 'Save' button in the Share task while still transferring an image to the cloud resulted in an upload error.  Separation of the scan in the middle of the scan.  Using 'Mirror' and 'Indexed Color' sometimes resulted in a vertical line in the middle of the scan.  Unified installation of Nextimage and the WIDEsystem driver did not ask for reboot when launched from USB key.  When printing to HP Designjet T7100 the active roll was used instead of the media selected.	30003	New	Improved auto size detection on iFLEX scanner.
Fix For IQ Quattro scanners the 'Light Source' option was sometimes hidden.  Scanning 'B&W Threshold' or 'B&W Adaptive' via TWAIN sometimes caused error.  Image on screen was shown with the printer's color calibration when copying using Closed Loop Calibration (CLC).  Installation did not always ask for admin rights even though they are required.  Fix For SD One scanners two scans were made if double clicking the 'Scan' button in the Share task.  For SD One scanners clicking the 'Save' button in the Share task while still transferring an image to the cloud resulted in an upload error.  Using the 'Descreening' resolution type on iFLEX together with auto size resulted in a large white area added to file.  Using 'Mirror' and 'Indexed Color' sometimes resulted in a vertical line in the middle of the scan.  Unified installation of Nextimage and the WIDEsystem driver did not ask for reboot when launched from USB key.  When printing to HP Designjet T7100 the active roll was used instead of the media selected.	27534	Fix	Gamma was sometimes changed to 5.0 when not using period as decimal
29026 Fix Scanning 'B&W Threshold' or 'B&W Adaptive' via TWAIN sometimes caused error.  29039 Fix Image on screen was shown with the printer's color calibration when copying using Closed Loop Calibration (CLC).  29543 Fix Installation did not always ask for admin rights even though they are required.  29861 Fix For SD One scanners two scans were made if double clicking the 'Scan' button in the Share task.  29865 Fix For SD One scanners clicking the 'Save' button in the Share task while still transferring an image to the cloud resulted in an upload error.  29879 Fix Using the 'Descreening' resolution type on iFLEX together with auto size resulted in a large white area added to file.  29919 Fix Using 'Mirror' and 'Indexed Color' sometimes resulted in a vertical line in the middle of the scan.  29963 Fix Unified installation of Nextimage and the WIDEsystem driver did not ask for reboot when launched from USB key.  30161 Fix When printing to HP Designjet T7100 the active roll was used instead of the media selected.			separator.
caused error.  Image on screen was shown with the printer's color calibration when copying using Closed Loop Calibration (CLC).  Installation did not always ask for admin rights even though they are required.  Fix For SD One scanners two scans were made if double clicking the 'Scan' button in the Share task.  Fix For SD One scanners clicking the 'Save' button in the Share task while still transferring an image to the cloud resulted in an upload error.  Vising the 'Descreening' resolution type on iFLEX together with auto size resulted in a large white area added to file.  Using 'Mirror' and 'Indexed Color' sometimes resulted in a vertical line in the middle of the scan.  Unified installation of Nextimage and the WIDEsystem driver did not ask for reboot when launched from USB key.  When printing to HP Designjet T7100 the active roll was used instead of the media selected.	28900	Fix	For IQ Quattro scanners the 'Light Source' option was sometimes hidden.
Fix Image on screen was shown with the printer's color calibration when copying using Closed Loop Calibration (CLC).  Fix Installation did not always ask for admin rights even though they are required.  Fix For SD One scanners two scans were made if double clicking the 'Scan' button in the Share task.  For SD One scanners clicking the 'Save' button in the Share task while still transferring an image to the cloud resulted in an upload error.  Using the 'Descreening' resolution type on iFLEX together with auto size resulted in a large white area added to file.  Using 'Mirror' and 'Indexed Color' sometimes resulted in a vertical line in the middle of the scan.  Unified installation of Nextimage and the WIDEsystem driver did not ask for reboot when launched from USB key.  When printing to HP Designjet T7100 the active roll was used instead of the media selected.	29026	Fix	Scanning 'B&W Threshold' or 'B&W Adaptive' via TWAIN sometimes
copying using Closed Loop Calibration (CLC).  Installation did not always ask for admin rights even though they are required.  Fix For SD One scanners two scans were made if double clicking the 'Scan' button in the Share task.  Fix For SD One scanners clicking the 'Save' button in the Share task while still transferring an image to the cloud resulted in an upload error.  Using the 'Descreening' resolution type on iFLEX together with auto size resulted in a large white area added to file.  Using 'Mirror' and 'Indexed Color' sometimes resulted in a vertical line in the middle of the scan.  Unified installation of Nextimage and the WIDEsystem driver did not ask for reboot when launched from USB key.  When printing to HP Designjet T7100 the active roll was used instead of the media selected.			caused error.
Fix Installation did not always ask for admin rights even though they are required.  Fix For SD One scanners two scans were made if double clicking the 'Scan' button in the Share task.  For SD One scanners clicking the 'Save' button in the Share task while still transferring an image to the cloud resulted in an upload error.  Using the 'Descreening' resolution type on iFLEX together with auto size resulted in a large white area added to file.  Using 'Mirror' and 'Indexed Color' sometimes resulted in a vertical line in the middle of the scan.  Unified installation of Nextimage and the WIDEsystem driver did not ask for reboot when launched from USB key.  When printing to HP Designjet T7100 the active roll was used instead of the media selected.	29039	Fix	Image on screen was shown with the printer's color calibration when
required.  Fix For SD One scanners two scans were made if double clicking the 'Scan' button in the Share task.  For SD One scanners clicking the 'Save' button in the Share task while still transferring an image to the cloud resulted in an upload error.  Using the 'Descreening' resolution type on iFLEX together with auto size resulted in a large white area added to file.  Using 'Mirror' and 'Indexed Color' sometimes resulted in a vertical line in the middle of the scan.  Unified installation of Nextimage and the WIDEsystem driver did not ask for reboot when launched from USB key.  When printing to HP Designjet T7100 the active roll was used instead of the media selected.			copying using Closed Loop Calibration (CLC).
Fix For SD One scanners two scans were made if double clicking the 'Scan' button in the Share task.  For SD One scanners clicking the 'Save' button in the Share task while still transferring an image to the cloud resulted in an upload error.  Using the 'Descreening' resolution type on iFLEX together with auto size resulted in a large white area added to file.  Using 'Mirror' and 'Indexed Color' sometimes resulted in a vertical line in the middle of the scan.  Unified installation of Nextimage and the WIDEsystem driver did not ask for reboot when launched from USB key.  When printing to HP Designjet T7100 the active roll was used instead of the media selected.	29543	Fix	Installation did not always ask for admin rights even though they are
button in the Share task.  For SD One scanners clicking the 'Save' button in the Share task while still transferring an image to the cloud resulted in an upload error.  Using the 'Descreening' resolution type on iFLEX together with auto size resulted in a large white area added to file.  Using 'Mirror' and 'Indexed Color' sometimes resulted in a vertical line in the middle of the scan.  Unified installation of Nextimage and the WIDEsystem driver did not ask for reboot when launched from USB key.  When printing to HP Designjet T7100 the active roll was used instead of the media selected.			required.
Fix For SD One scanners clicking the 'Save' button in the Share task while still transferring an image to the cloud resulted in an upload error.  Using the 'Descreening' resolution type on iFLEX together with auto size resulted in a large white area added to file.  Using 'Mirror' and 'Indexed Color' sometimes resulted in a vertical line in the middle of the scan.  Unified installation of Nextimage and the WIDEsystem driver did not ask for reboot when launched from USB key.  When printing to HP Designjet T7100 the active roll was used instead of the media selected.	29861	Fix	For SD One scanners two scans were made if double clicking the 'Scan'
still transferring an image to the cloud resulted in an upload error.  Using the 'Descreening' resolution type on iFLEX together with auto size resulted in a large white area added to file.  Using 'Mirror' and 'Indexed Color' sometimes resulted in a vertical line in the middle of the scan.  Unified installation of Nextimage and the WIDEsystem driver did not ask for reboot when launched from USB key.  When printing to HP Designjet T7100 the active roll was used instead of the media selected.			button in the Share task.
Fix Using the 'Descreening' resolution type on iFLEX together with auto size resulted in a large white area added to file.  Using 'Mirror' and 'Indexed Color' sometimes resulted in a vertical line in the middle of the scan.  Fix Unified installation of Nextimage and the WIDEsystem driver did not ask for reboot when launched from USB key.  When printing to HP Designjet T7100 the active roll was used instead of the media selected.	29865	Fix	For SD One scanners clicking the 'Save' button in the Share task while
resulted in a large white area added to file.  29919  Fix  Using 'Mirror' and 'Indexed Color' sometimes resulted in a vertical line in the middle of the scan.  29963  Fix  Unified installation of Nextimage and the WIDEsystem driver did not ask for reboot when launched from USB key.  When printing to HP Designjet T7100 the active roll was used instead of the media selected.			still transferring an image to the cloud resulted in an upload error.
29919 Fix Using 'Mirror' and 'Indexed Color' sometimes resulted in a vertical line in the middle of the scan.  29963 Fix Unified installation of Nextimage and the WIDEsystem driver did not ask for reboot when launched from USB key.  30161 Fix When printing to HP Designjet T7100 the active roll was used instead of the media selected.	29879	Fix	Using the 'Descreening' resolution type on iFLEX together with auto size
the middle of the scan.  29963 Fix Unified installation of Nextimage and the WIDEsystem driver did not ask for reboot when launched from USB key.  30161 Fix When printing to HP Designjet T7100 the active roll was used instead of the media selected.			resulted in a large white area added to file.
29963 Fix Unified installation of Nextimage and the WIDEsystem driver did not ask for reboot when launched from USB key.  30161 Fix When printing to HP Designjet T7100 the active roll was used instead of the media selected.	29919	Fix	Using 'Mirror' and 'Indexed Color' sometimes resulted in a vertical line in
for reboot when launched from USB key.  30161 Fix When printing to HP Designjet T7100 the active roll was used instead of the media selected.			the middle of the scan.
30161 Fix When printing to HP Designjet T7100 the active roll was used instead of the media selected.	29963	Fix	Unified installation of Nextimage and the WIDEsystem driver did not ask
the media selected.			for reboot when launched from USB key.
	30161	Fix	When printing to HP Designjet T7100 the active roll was used instead of
Fix Several user interface corrections.			the media selected.
		Fix	Several user interface corrections.

#### Changes in version 4.3.1

29936	Fix	Various problems in Nextimage TWAIN driver.
29989		

28725	New	Unified installation of Nextimage and the WIDEsystem driver (when the WIDEsystem package is placed in a WS subfolder). The two applications need to be individually uninstalled e.g. if downgrading an installation.
29639	New	Automatic software update notification (for selected scanner models).

29665	New	Free-edition for SD One scanners with simplified Scan task and new Share
		task for scanning to cloud services.
29666	New	Improved auto black/white point detection.
29681	New	Support for Canon iPF670/671/770/771.
29720	New	Support for HP Designjet T7200/T7200PS.
29641	Fix	Preview using HP T7100 printer resulted in an error message.
29763	Fix	Polish help was unreadable.
29790	Fix	Compensate for margins did not always work as intended on Canon
		printers.

## Changes in version 4.2.1

28983	Fix	Using auto size on iFLEX above 600dpi resulted in wrong size.
29335	Fix	Printing a multipage document resulted in first page being printed multiple
		times and none of the other pages being printed.
29335	Fix	Improved stitching of oversize scans (scans larger than A2/C-size) on
		flatbed scanner.
29398	Fix	Scanner name was not updated when activating the scanner (license)
29622		while the program was running.
29438	Fix	Saving an opened 1bit file resulted in an 8bit file and sometimes an error
29531		message.
	Fix	Several user interface corrections.

	New	Support for 'The New ScanStation', including new 'History' feature.
28746	New	List of Release Notes now accessible from Help menu.
28895	New	New button in 'On Screen Keyboard' (in Touch Screen mode) to switch
		keyboard between selected language and English. The feature allows
		entering English names and destinations for all languages.
28908	New	New touch-friendly browse dialog in Touch Screen mode.
28943	New	New preset option in 'Save in' panel for often used folder and network destinations.
29110	New	Support for HP Designjet T3500 and Z5400.
29157	New	Improved deskew detection when using 'Auto Alignment'.
29494	New	Improved speed of LZW compression.
28661	Fix	When entering 'File name', the template field <mypictures> was</mypictures>
		allowed.
28770	Fix	'ISO B' was sometimes default in 'First Time Setup' dialog.
28802	Fix	'Image Changed' dialog was sometimes shown behind the main window.
28891	Fix	When copying B&W or grayscale to HP Desingjet Z3200 an error
		occurred.
28954	Fix	Opening file with .jpeg extension caused Nextimage to crash.
29092	Fix	Using Sharpen (in Image Adjustments) sometimes caused Nextimage to
		become unresponsive.
29098	Fix	Making a CLC profile for Canon iPF820 resulted in an error.
29100	Fix	When making a CLC profile sometimes an error occurred.
29102	Fix	Sometimes Nextimage did not start correctly, showing a red cross in lower
		right corner.
29109	Fix	Cancel reacted very slowly.
29333	Fix	When paper jam occurred during Copy then print job was still sent to printer.

29337	Fix	When using ATAC (scanning thick originals) with 'Auto Size' no scanning was performed.
29352	Fix	It was possible to generate invalid TIF files above 4GB.
29377	Fix	Resize (in Image Adjustments) to fixed size was not working when using auto input size.
29423	Fix	Using Manual Align (in Image Adjustments) and fixed input size resulted in a corrupt file.
	Fix	Several user interface corrections.

## Changes in version 4.1.2

28769	New	Improved A1/D-size scans on iFLEX flatbed scanners.
28829	New	Improved 'Auto Size' on iFLEX flatbed scanners.
28881	New	Improved 'Auto Alignment'.
27454	Fix	Aligning the image could cause jaggy lines.
27597	Fix	1-261 error could occur followed by the program being unresponsive.
28722	Fix	Splash screen was sometimes displayed too long when using TWAIN.

## Changes in version 4.1.1

28069	New	Support for Canon iPF680/685/780/785, iPF
28458		6400SE/6410SE/8400SE/8410SE
28566	New	Allow image adjustments when using Indexed Color.
28507	New	Support for HP DesignjetT795/T795ps, Designjet
28567		Z6600/Z6600ps/Z6800/Z6800ps
27721	New	Startup in TWAIN mode after Windows reboot if Nextimage was last used in
		TWAIN mode.
28461	New	Support for Océ Plotwave 750
28568	New	Support for Epson SC-T3200/T5200/T5200D/T7200/T7200D
27575	Fix	Using 'Reset all Settings' caused paper frame to disappear from current
		scan.
27620	Fix	Using 'Auto Length', but not 'Auto Width', on iFlex scanner resulted in wrong
		scan area.
28236	Fix	Sometimes unable to use scanner after Nextimage restored from
		Notification Area.
28332	Fix	Cancelling 'No Media' dialog caused Nextimage to become unresponsive.
28500	Fix	Scans with rotation sometimes resulted in error.
28518	Fix	Making Indexed Color preview in TWAIN caused Nextimage to become
		unresponsive.
28598	Fix	Making Indexed Color Copy sometimes caused Nextimage to become
		unresponsive.
28624	Fix	Not possible to select printers using Windows drivers. Only printers using
		application

27267	New	Performance and memory usage improved.
22490	New	Supported Canon media for different medias merged into common list, to
		avoid the need for specifying region in printer settings.
25868	New	Sharpen and Smoothen Image Adjustments added to B&W Threshold
		Image Type.
26496	New	Search for scanner during application start-up now continues until one is
		found or user cancel search.

27315	New	Added 'From name' to 'Email Setup'
27389	New	Display of Help now integrated in application instead of using default web
		browser.
27417	New	Default compression for CALS file format changed to Type 1.
27455	New	Bi-directional communication to HP Designjet T920, T1500, T2500 for
		reading installed media etc.
27924	New	Default of 'Auto size to' changed to 'Any size'.
27392	Fix	Some predefined presets did not include the state for 'Auto' option of B&W
		Points.
27466	Fix	It was not possible to remove a created 'Output ICC profile'.
27553	Fix	Using 'Align to Measure Line' in the Rotate/Mirror panel with a vertical
		measure line caused image to be rotated 90°.
28160	Fix	Printing to HP T610 did not work.
28162	Fix	Pressing the (green) Start button on the iFlex scanner while the
		application was not running caused an error.
28183	Fix	Colors in auto palette could be bad dependent on setup in 24 bit Color.
28221	Fix	Starting application from Notification Area with a scanner in sleep caused
		an error.
28226	Fix	Indexed color gave 24 bit file if using Manual Palette and 'Apply palette in view' was not checked.
28260	Fix	Exceeding maximum length or width of 200 inches when writing PDF files did not show a message.
28277	Fix	Selecting a very small area in the image viewer while using Sharpen could cause a crash.
28303	Fix	If scanning to a multipage file after scanning to certain single page formats
		resulted in the first scan being saved to a single page file.
28354	Fix	It was not possible to use the application from multiple logged in users on the same PC.
28361	Fix	Pressing Scan button quickly after changing a setting could cause an error.
		Several user interface corrections.

## Changes in version 4.0.3

27885	New	Advanced dimensional corrections (Accuracy Lens Enhancement and
		Enhance Horizontal Accuracy) are now disabled by default.
27752	Fix	After use of auto size, subsequent scans would be missing the top edge of
		the image.
27762	Fix	Scanning using B&W Adaptive in high resolution could cause an
		application error.
27811	Fix	Waking scanner after sleep could cause an application error.
27827		
27862	Fix	Scanning on a monochrome scanner caused an application error.
27898	Fix	Saving multipage files in the File task caused an application error.

27314	New	Allow preview when scanning to email or TWAIN.
27386	New	Support for HP Designjet Z5400.
27533	New	Warn users during install if new license key will be needed.

27586	New	Individual set of predefined presets for CIS and CCD scanners.
27617	Fix	Opening a multipage file could change file type for subsequent scans.
27678	Fix	Partial image remained in viewer if scan was cancelled.
27672	Fix	Using Autosize in the TWAIN driver could cause an application error.
27707	Fix	Starting TWAIN driver could fail.
27737	Fix	Sharpen, Smoothen and B&W Adaptive was not always applied correctly
		to image during scan to file (introduced in 4.0.1).

## Changes in version 4.0.1

27400	New	Support for Epson SC-T3050/5050/7050, SC-T3070/5070/7070, SC-T3080/5080/7080.
27558	New	30 days trial period when installed on PCs with older versions.
27488	Fix	The Product Improvement Program dialog could be displayed before
		Nextimage was visible.
27494	Fix	Auto size selection was not remembered after a Windows reboot.
27505	Fix	Compensate for printer margins did not always have the desired effect.
27520	Fix	Accounting statistics did not include oversize scans (scans larger than
		A2/C-size) on flatbed scanner.
27522	Fix	Improved display quality of Sharpen, Smoothen and B&W Adaptive when
		zoomed out in image view.
	Fix	Miscellaneous user interface corrections.

26694	New	Support for new Contex HD iFLEX scanners.
26895	New	SnapScan workflow for improved performance.
26903	New	Support for HP Designjet T2500.
26956	New	Scan up to A1/D-size document on an A2/C-size flatbed scanner.
26959	New	Improved startup speed by minimizing application to Windows Notification Area.
26960	New	Integrated email functionality using SMTP.  Note that to send emails larger than 3 MB Microsoft .NET Hotfix
27032	New	KB2183292 is required.  Support for Canon iPF64x0S, iPF84x0S.
27149	New	Redesigned application help, and translation added for Dutch, Italian and Korean.
27174	New	Support for Mutoh RJ-900X, RJ-901X.
27266	New	Improved speed when saving to TIF files using LZW compression.
27426	New	Improved speed when saving to file.
26079	Fix	Missing warning when closing application with edited image in the File Task.
26689	Fix	No media in Canon iPF820 caused an application error.
26796	Fix	Printing on a Canon iPF750 using USB could cause an application error.
27119	Fix	Descreening and Turbo resolution modes could generate files with wrong resolution.
27175	Fix	Media list contained invalid medias for Océ ColorWave and PlotWave printers.
27215	Fix	Mixing color and monochrome pages in PDF/A multipage files caused an application error.
		Several user interface corrections.

#### **Supported Operating Systems**

- Windows Vista (Business) 32-bit
- Windows Vista (Business) 64-bit
- Windows 7 (Enterprise) 32-bit
- Windows 7 (Enterprise) 64-bit
- Windows Server 2008 (Standard Edition), 64-bit
- Windows 8.1 (Enterprise) 32-bit
- Windows 8.1 (Enterprise) 64-bit
- Windows 10 (Enterprise) 32-bit
- Windows 10 (Enterprise) 64-bit

#### **Supported Scanners**

- IQ 2420
- IQ 2490
- IQ 4420
- IQ 4450
- IQ 4490
- CG710
- CG810
- IQ Quattro 2420
- IQ Quattro 2450
- IQ Quattro 2490u
- IQ Quattro 2490
- IQ Quattro 4420
- IQ Quattro 4450
- IQ Quattro 4490u
- IQ Quattro 4490
- SD One 24
- SD One 24+
- SD One 36
- SD One 36+

- SD3610
- SD3610+
- SD3615 MFP
- SD3619
- SD3620
- SD3650+
- SD3690+
- SD4410
- SD4420
- SD4430
- SD4450
- SD4490
- XD2490
- HD Ultra 3610
- HD Ultra 3610+
- HD Ultra 3610i
- HD Ultra 3610i+
- HD Ultra 3630
- HD Ultra 3630+
- HD Ultra 3630i
- HD Ultra 3630i+
- HD Ultra 4210
- HD Ultra 4210+
- HD Ultra 4210i
- HD Ultra 4210i+
- HD Ultra 4230
- HD Ultra 4230+
- HD Ultra 4230i
- HD Ultra 4230i+
- HD Ultra 3650+
- HD Ultra 3650i+
- HD Ultra 3690i+

- HD Ultra 4250+
- HD Ultra 4250i+
- HD Ultra 4290i+
- HD Ultra i3610s
- HD Ultra i3620s
- HD Ultra i3650s
- HD Ultra i3690s
- HD Ultra i4210s
- HD Ultra i4220s
- HD Ultra i4250s
- HD Ultra i4290s
- HD iFLEX
- HD iFLEXu
- HD3630
- HD3630+
- HD3650
- HD3650+
- HD4230
- HD4230+
- HD4250
- HD4250+
- HD5430
- HD5430+
- HD5450
- HD5450+

#### **Supported Printers**

The application supports the below range of printers. If you do not find the relevant printer in the list, many other printers are indirectly supported by creating your own Printer Profile, or by printing to a hot-folder.

- Canon BJ-W3000
- Canon BJ-W3050

- Canon BJ-W7000
- Canon iPF500
- Canon iPF510
- Canon iPF600
- Canon iPF605
- Canon iPF610
- Canon iPF650 (qualified with Plain Paper and Coated Paper only)
- Canon iPF655 (qualified with Plain Paper and Coated Paper only)
- Canon iPF670
- Canon iPF671
- Canon iPF680
- Canon iPF685
- Canon iPF700
- Canon iPF710
- Canon iPF720
- Canon iPF750 (qualified with Plain Paper and Coated Paper only)
- Canon iPF755 (qualified with Plain Paper and Coated Paper only)
- Canon iPF760
- Canon iPF765
- Canon iPF770
- Canon iPF771
- Canon iPF780
- Canon iPF785
- Canon iPF810 (qualified with Plain Paper and Coated Paper only)
- Canon iPF815 (qualified with Plain Paper and Coated Paper only)
- Canon iPF820 (qualified with Plain Paper and Coated Paper only)
- Canon iPF825 (qualified with Plain Paper and Coated Paper only)
- Canon iPF5000
- Canon iPF5100
- Canon iPF6000S
- Canon iPF6100
- Canon iPF6200

- Canon iPF6300
- Canon iPF6350
- Canon iPF6300S
- Canon iPF64x0S
- Canon iPF64x0SE
- Canon iPF8000
- Canon iPF8000S
- Canon iPF8100
- Canon iFP8300
- Canon iPF8300S
- Canon iPF8310
- Canon iPF8310S
- Canon iPF84x0S
- Canon iPF84x0SE
- Canon iPF9000
- Canon iPF9000S
- Canon iPF9100
- Canon W6200PG
- Canon W6400D
- Canon W6400PG
- Canon W7200
- Canon W8200
- Canon W8200PG
- Canon W8400
- Canon W8400D
- Canon W8400PG
- Canon PRO-1000
- Canon PRO-500
- Canon PRO-2000
- Canon PRO-4000
- Canon PRO-520
- Canon PRO-540

- Canon PRO-4000S
- Canon PRO-6000S
- Canon PRO-540S
- Canon PRO-560S
- Encad NovaJet 500
- Encad NovaJet 630
- Encad NovaJet 700
- Encad NovaJet 750
- Encad NovaJet 850
- Encad NovaJet 1000i
- Encad NovaJet PRO 600e
- Encad NovaJet PRO
- Encad NovaJet PROe
- Epson Stylus Pro 4400
- Epson Stylus Pro 4800
- Epson Stylus Pro 7000
- Epson Stylus Pro 7400
- Epson Stylus Pro 7600
- Epson Stylus Pro 7700
- Epson Stylus Pro 7710
- Epson Stylus Pro 7800
- Epson Stylus Pro 7880
- Epson Stylus Pro 7880C
- Epson Stylus Pro 7890
- Epson Stylus Pro 7900
- Epson Stylus Pro 7910
- Epson Stylus Pro 9000
- Epson Stylus Pro 9400
- Epson Stylus Pro 9600
- Epson Stylus Pro 9700
- Epson Stylus Pro 9710
- Epson Stylus Pro 9800

- Epson Stylus Pro 9880
- Epson Stylus Pro 9880C
- Epson Stylus Pro 9890
- Epson Stylus Pro 9900
- Epson Stylus Pro 9910
- Epson Stylus Pro 10000
- Epson Stylus Pro 10600
- Epson Stylus Pro 11880
- Epson Stylus Pro 11880C
- Epson SureColor SC-P6000
- Epson SureColor SC-P7000
- Epson SureColor SC-P8000
- Epson SureColor SC-P9000
- Epson SureColor SC-T3000
- Epson SureColor SC-T3200
- Epson SureColor SC-T3200D
- Epson SureColor SC-T3250
- Epson SureColor SC-T3250D
- Epson SureColor SC-T3270
- Epson SureColor SC-T3270D
- Epson SureColor SC-T5000
- Epson SureColor SC-T5200
- Epson SureColor SC-T5200D
- Epson SureColor SC-T5250
- Epson SureColor SC-T5250D
- Epson SureColor SC-T5270
- Epson SureColor SC-T5270D
- Epson SureColor SC-T7000
- Epson SureColor SC-T7200
- Epson SureColor SC-T7200D
- Epson SureColor SC-T7250
- Epson SureColor SC-T7250D

- Epson SureColor SC-T7270
- Epson SureColor SC-T7270D
- Gestetner GWD2004
- Gestetner GWD2006
- Gestetner SP W2470
- HP DesignJet 70
- HP DesignJet 90
- HP DesignJet 110
- HP DesignJet 111
- HP DesignJet 120
- HP DesignJet 130
- HP DesignJet 500 (HP-GL/2)
- HP DesignJet 500PS (HP-GL/2)
- HP DesignJet 510 (HP-GL/2)
- HP DesignJet 510PS (HP-GL/2)
- HP DesignJet 750C
- HP DesignJet 800
- HP DesignJet 800PS
- HP DesignJet 1050C
- HP DesignJet 1055CM
- HP DesignJet 2000CP
- HP DesignJet 2500CP
- HP DesignJet 3000CP
- HP DesignJet 3500CP
- HP DesignJet 4000
- HP DesignJet 4000ps
- HP DesignJet 4020
- HP DesignJet 4020ps
- HP DesignJet 4500
- HP DesignJet 4500mfp
- HP DesignJet 4500ps
- HP DesignJet 4520

- HP DesignJet 4520mfp
- HP DesignJet 4520ps
- HP DesignJet 5000
- HP DesignJet 5000PS
- HP DesignJet 5500
- HP DesignJet 5500PS
- HP DesignJet T610
- HP DesignJet T610ps
- HP DesignJet T620
- HP DesignJet T620ps
- HP DesignJet T730
- HP DesignJet T770
- HP DesignJet T770ps
- HP DesignJet T770 24
- HP DesignJet T770ps 24
- HP DesignJet T790
- HP DesignJet T790ps
- HP DesignJet T795
- HP DesignJet T795ps
- HP DesignJet T830 MFP
- HP DesignJet T920
- HP DesignJet T920ps
- HP DesignJet T930
- HP DesignJet T930ps
- HP DesignJet T1100
- HP DesignJet T1100ps
- HP DesignJet T1120
- HP DesignJet T1120mfp
- HP DesignJet T1120ps
- HP DesignJet T1200
- HP DesignJet T1200ps
- HP DesignJet T1300

- HP DesignJet T1300ps
- HP DesignJet T1500
- HP DesignJet T1500ps
- HP DesignJet T1530
- HP DesignJet T1530ps
- HP DesignJet T2300
- HP DesignJet T2300ps
- HP DesignJet T2500
- HP DesignJet T2500ps
- HP DesignJet T2530
- HP DesignJet T2530ps
- HP DesignJet Z2100
- HP DesignJet Z2110
- HP DesignJet Z2110
- HP DesignJet Z2600
- HP DesignJet Z2600ps
- HP DesignJet Z3100ps
- HP DesignJet Z3200
- HP DesignJet Z3200ps
- HP DesignJet Z5200
- HP DesignJet Z5200ps
- HP DesignJet Z5400
- HP DesignJet Z5400ps
- HP DesignJet Z6100
- HP DesignJet Z6100ps
- HP DesignJet Z6200
- HP DesignJet Z6200ps
- HP DesignJet Z5600
- HP DesignJet Z5600ps
- HP DesignJet Z6600
- HP DesignJet Z6600ps
- HP DesignJet Z6800

- HP DesignJet Z6800ps
- HP DesignJet T7100
- HP DesignJet T7100ps
- HP DesignJet T7200
- HP DesignJet T7200ps
- HP PageWide XL 4000
- HP PageWide XL 4000 MFP
- HP PageWide XL 4000PS
- HP PageWide XL 4000PS MFP
- HP PageWide XL 4500
- HP PageWide XL 4500 MFP
- HP PageWide XL 4500PS
- HP PageWide XL 4500PS MFP
- HP PageWide XL 5000
- HP PageWide XL 5000 Blueprinter
- HP PageWide XL 5000 MFP
- HP PageWide XL 5000PS
- HP PageWide XL 5000PS Blueprinter
- HP PageWide XL 5000PS MFP
- HP PageWide XL 8000 Blueprinter
- HP PageWide XL 8000PS
- HP PageWide XL 8000PS Blueprinter
- Imagio MP W3600
- Imagio MP W2400
- Lanier LP124w
- Lanier LW324
- Lanier LW326
- Mutoh RJ-900C
- Mutoh RJ-901C
- Mutoh RJ-900X
- Mutoh RJ-901X
- Mutoh RJ-4000

- Mutoh RJ-4100
- Mutoh RJ-8000
- NRG MP W2400
- NRG MP W3600
- NRG SP W2470
- Océ 535X-42
- Océ 535X-60
- Océ 535X-600-42
- Océ 535X-600-60
- Océ ColorWave 300
- Océ ColorWave 500
- Océ ColorWave 550
- Océ ColorWave 600
- Océ ColorWave 650
- Océ ColorWave 700
- Océ ColorWave 810
- Océ ColorWave 900
- Océ ColorWave 910
- Océ CS5050
- Océ CS5070
- Océ PlotWave 300
- Océ PlotWave 340
- Océ PlotWave 350
- Océ PlotWave 360
- Océ PlotWave 500
- Océ PlotWave 750
- Océ PlotWave 900
- Océ TCS300
- Océ TCS400
- Océ TCS500
- Océ TDS300
- Océ TDS320

- Océ TDS400
- Océ TDS450
- Océ TDS600
- Océ TDS700
- Océ TDS750
- Océ TDS800
- Océ TDS860
- Ricoh Aficio MP W2400
- Ricoh Aficio MP W3600
- Ricoh Aficio SP W2470
- Roland Hi-Fi JET FJ-40
- Roland Hi-Fi JET FJ-50
- Roland Hi-Fi JET FJ-540
- Roland Hi-Fi JET FJ-740
- Savin 2404WD
- Savin 2404WDP
- Savin 2406WD
- Seiko LP-1010
- Selex SG-950T
- Xerox 6204
- Xerox 8825
- Xerox 8830