

GUIDELINES FOR FIRMWARE UPLOADING

You need: USB cable, Boot jumper, Windows PC


What does the Windows PC need?

USB driver must be installed on the PC. USB driver can be downloaded at <http://metos.at/firmware-download/> (use your Fieldclimate credentials to login). For all the other operative systems please download it at <https://www.silabs.com>.


Install the tool **PI Firmware uploader** (please find attached the file *PI-FW-uploader-1.120* or download it at <http://metos.at/firmware-download/>)

To manually upload the firmware on the station, please follow the given next steps:


1. Unplug the battery and solar panel.
2. Plug in the USB cable and set the Boot jumper (red circle). Make sure that there are not other USB cables connected to your PC.



3. Plug in the battery (blue circle).




iMETOS 3.3 motherboard




iMETOS ECO D3 motherboard

4. Check that the station is in boot mode and install the tool **PI Firmware uploader** (please find attached the file **PI-FW-uploader-1.110** or download it at <http://metos.at/firmware-download/>). Yellow LED in the middle is on (see figure below). If the station is not in boot mode, press *Reset*







(5) Click “Upload FW”.



(5) After “Firmware successfully uploaded”, the board automatically restarts and starts communication with the web. Wait until the first communication ends “>> **Success**”.

As soon as you see the message “Firmware successfully uploaded”, you’re done.

Note: Leave the battery connected for 24 hours. Connection with the server will be established after a while.



(6) To leave the boot menu/boot mode click "Close Port", remove the Boot jumper, remove the USB cable and press reset on the board.

