Contex LINK change Log

Contents

Version Changes

Changes in version 2.77698

77439	New	Support for new scanner
33780	Fix	Remove button did not work properly
34177	Fix	Fields in the main window list was by mistake editable
77432	Fix	Close button in system menu did not work

Changes in version 1.70029

	New	Initial release
	New	

Supported Scanners

The Contex LINK software supports the following scanners.

- SD One MF
- IQ FLEX