Changes in 2.3

32948	New	Canon PRO 1000/500/2000/4000/520/540/4000S/6000S/540S/560S added (network only).
32549	New	Support for HP DesignJet Z2600/Z5600 added.

Changes in 2.2

32064	Fix	Sometimes calibration failed
32555	Fix	Sometimes multiple copies failed on Canon iPF printers
32564	New	Support for Canon iPF6400E

Changes in 2.1

27985	Fix	HP Designjet T930/T1530/T2530 were not always recognized and installed correctly

Changes in 2.0

31127	New	Support for HP Designjet T730/T830 MFP.
31237	New	Support for HP Designjet T930/T1530/T2530
27339 31128	New	Support for Epson Stylus Pro 7710, 7880, 7880C, 7890, 7900, 7910, 9710, 9880, 9880C, 9890, 9900, 9910, 11880, 11880C and Epson SureColor SC-P6000, SC-P7000, SC-P8000, SC-P9000.

Changes in 1.9

30389	Fix	Fixed size scans were offset from center on some scanner models
31033	Fix	After a calibration camera images could be misaligned on some 24" scanners

Changes in 1.8

28508	New	Support for HP Designjet D5800, D5800ps,T3500, T7200 and T7200ps

28070	New	Support for Canon iPF670, iPF671, iPF686, iPF770 and iPF771
30144	New	Support for Canon iPF830, iPF840 and iPF850
28672	Fix	Correction of camera alignment variations during scanning on CIS scanners
29618	Fix	Incorrect crop area was saved in file
29854	Fix	Multiple email presets were not displayed correctly
30316	Fix	Support for loading cut sheet media on various HP printers
29058	Fix	SMTP setup was corrupted after system update
29168	Fix	Improved language support for Chinese, Japanese and Korean
28853	Fix	Not all settings were reset to default at inactivity timeout
	Fix	For some HP Designjet printers the media type information was missing
	Fix	Several corrections to translations

Changes in 1.7

28508	New	Support for HP Designjet T795, T795ps, Z6600 and Z6800
28070	New	Support for Canon iPF680, iPF681, iPF685, iPF780, iPF781, iPF785 and iPF786
28460	New	Support for Canon iPF6400SE, 6410SE, 8400SE and 84100SE
28569	New	Support for Epson SC-T3200/T5200/T5200D/T7200/T7200D
28336	New	Support for new touch screen panel (1366x768)
28509	Fix	For HP Designjet Z5200 some media types were unsupported
28335	Fix	Email and Network setup didn't work with some localized onscreen keyboards

Changes in 1.6

	Fix	

	New	Support for new CIS scanners
	New	Support for Canon iPF8400S
28111	Fix	HP Designjet T920, T1500,T2500 displayed incorrect media names
28173	Fix	Sometimes installation of the same printer model failed
28143	Fix	HP Designjet T610 support was broken

Changes in 1.5

27399	New	Support for regional versions of EPSON SC-T3000/5000/7000
27387	New	Support for HP Designjet Z5400
26923	New	Support for HP Designjet T920, T1500 and T2500
27342	New	Support printers connected via network
27514	New	Improved automatic paper size detection
27340	New	SSL encryption added to Email Setup
	Fix	Scanner paper offsets didn't allow negative values
	Fix	Compensate for margins didn't always select correct paper width

Changes in 1.4

26640	New	Support for file format PDF/A added
26825	New	Support for Canon iPF6400, 6450, 8400, 9400 and 9400S
26918	New	Support for HP Designjet 500 and 510
26803	Fix	Support for Epson SC-T3000/5000/7000 was missing after system upgrade
26852	Fix	Network configuration adjusted to support communication with devices using older operating systems.
26763	Fix	For some Canon printers, support for Tracing paper (CAD) and Matt film (CAD) was missing

26688	Fix	Using Canon iPF820 without paper loaded could cause an application crash
26678	Fix	For some Canon printers, media names were not translated correctly
26622	Fix	Sometimes the LAN destination failed to connect after using the 'Test Connection' button
26313	Fix	CALS file format changed from type 4 to type 1
26259	Fix	Printers were not always recognized and installed correctly
26058	Fix	Scanning above 600 dpi failed on an SD3615

Changes in 1.3

26333	New	'Compensate for margins' option under Basic Options. This allows print to stay same size as original.
26332	New	Support for Epson SC-T3000/5000/7000
	New	'Auto size to' option under Basic Options is now available for all scanner models.
26334	New	'Auto size to' now also snaps the scan in the length direction to selected standard series.
	New	Enable ping and tracert enabled for support purposes
26440	Fix	The MAC address under Network options was not displayed if Ethernet cable was disconnected
26493	Fix	HP Designjet T120 showed an empty printer media list
	Fix	Several corrections to translations

Changes in 1.2

26182	New	Printer Media types translated in Japanese, French, Italian, German, Spanish, Korean, Simplified Chinese and Russian on Canon iPF650, iPF655, iPF750, iPF755, iPF6300, iPF6350, Canon iPF8300, Canon iPF8310, iPF8310, iPF6300S, iPF8300S, iPF8310S, iPF760 and iPF765
26180	New	Change log info added to 'About' dialog
26169	Fix	Sometimes incorrect CLC profiles were generated or an error message reporting incorrect color patch reading was displayed
25981	Fix	Default Copy quality setting changed to 'Fast'
25973	Fix	Unable to cancel print jobs in spooler
26220	New	Automatic scanner firmware download implemented

Changes in 1.1

	New	Support for HP Designjet T120 and T520

	New	Support for Epson Stylus Pro 7700 and 9700
	New	Support for Mutoh RJ900X, RJ901X, RJ900C and RJ901C
	Fix	Several corrections to translations
	Fix	Timeout during Touch calibration could give incorrect result

Changes in 1.0

	Fix	Improved language support for Chinese, Japanese, Polish and Russian

Changes in 1.0.12

	New	Initial version of the MFP2GO software