

HD Ultra X Release Notes

Supported products

List of scanner product types supported by the firmware.

- HD Ultra X 6000 (RB67G)
- HD Ultra X 4200 (RC67G)
- HD Ultra X 3600 (RC67G)

Version Changes

Changes in version 3.8.2 - 001

- Support for new Nextimage 7 license system.

Changes in version 3.8.1 - 025

- Support for updated SUX board (SUX32)

Changes in version 3.8.1 - 022

- Support for Multi Exposure scanning (requires WIDEsystem 6 & Nextimage 6)
- ICC Profile naming changed to comply with FADGI implementation

Changes in version 3.8.1 - 020

- Optimized CCD sampling time for the CBV camera board.

Changes in version 3.8.1 - 019

- Improved calibration for scanners with the CBV camera board.

Changes in version 3.8.1 - 017

- Improved camera to camera matching.

Changes in version 3.8.1 - 015

- Sometimes scans in 1200 dpi gray mode gave image artefacts.
- Improved calibration stability.

Changes in version 3.8.1 - 014

- Sometimes the CBV camera board created bad image quality

Changes in version 3.8.1 - 013

- Support for the CBV camera board

Changes in version 3.8.1 - 012

- Support for the Macronix flash device

Changes in version 3.8.1 - 010

- Improved stop/start default value for HDUX 42"

Changes in version 3.8.1 - 009

- Support for the 4 new Rightcolor models for Joysail
 - Rightcolor R3160
 - Rightcolor R3180
 - Rightcolor R4160
 - Rightcolor R4180

Changes in version 3.8.1 - 008

- Allow read of fwupdate status in warming up state

Changes in version 3.8.1 - 006

- Support for IQ Quattro X
- Sometimes network communication failed while scanning