

## Contex LINK change Log

### Contents

[Version Changes](#)

[Supported Scanners](#)

### Version Changes

#### Changes in version 5.86116

|       |     |   |
|-------|-----|---|
| 35314 | New | Easy reorder of folder in Setup Folders dialog                    |
| 36357 | New | System tray notifications are not stored in Windows Action Center |
| 35042 | Fix | Translation of additional texts                                   |
| 36387 | Fix | Dialogs are adjusted to 4K displays                               |
| 36352 | Fix | Login to Dropbox never ended                                      |

#### Note to support team:

The Web connection in Contex Link 5 or higher requires that the latest display driver software is being used on Windows 7 (32 and 64 bit). The customer may experience that the link crashes or hangs when the logon screen should be displayed if the operating system is using an old display driver.

#### Changes in version 4.81409

|       |     |                                     |
|-------|-----|-------------------------------------|
| 34700 | Fix | Scan to cloud services did not work |
|-------|-----|-------------------------------------|

#### Changes in version 3.79450

|       |     |  |
|-------|-----|--|
| 34698 | New | Verified Publisher displayed in Windows security warning |
| 34651 | New | Hint texts in Setup are now translated                   |

#### Changes in version 2.77698

|       |     |  |
|-------|-----|--|
| 77439 | New | Support for new scanner                                |
| 33780 | Fix | Remove button did not work properly                    |
| 34177 | Fix | Fields in the main window list was by mistake editable |
| 77432 | Fix | Close button in system menu did not work               |

#### Changes in version 1.70029

|  |     |                 |
|--|-----|-----------------|
|  | New | Initial release |
|  | New |                 |

### Supported Scanners

The Contex LINK software supports the following scanners.

- SD One MF
- IQ FLEX