

Contex LINK change Log

Contents

[Version Changes](#)

[Supported Scanners](#)

Version Changes

Changes in version 6.89919

36416	New	Host icons on the Setup dialog shows a green checkmark when connection is authenticated.
37084	Fix	Dropbox authentication failed.
37047	Fix	Microsoft OneDrive connection stopped working.
37044	Fix	Profile picture sometimes failed to load.

Changes in version 5.86116

35314	New	Easy reorder of folder in Setup Folders dialog
36357	New	System tray notifications are not stored in Windows Action Center
35042	Fix	Translation of additional texts
36387	Fix	Dialogs are adjusted to 4K displays
36352	Fix	Login to Dropbox never ended

Note to support team:

The Web connection in Contex Link 5 or higher requires that the latest display driver software is being used on Windows 7 (32 and 64 bit). The customer may experience that the link crashes or hangs when the logon screen should be displayed if the operating system is using an old display driver.

Changes in version 4.81409

34700	Fix	Scan to cloud services did not work
-------	-----	-------------------------------------

Changes in version 3.79450

34698	New	Verified Publisher displayed in Windows security warning
34651	New	Hint texts in Setup are now translated

Changes in version 2.77698

77439	New	Support for new scanner
33780	Fix	Remove button did not work properly
34177	Fix	Fields in the main window list was by mistake editable
77432	Fix	Close button in system menu did not work

Changes in version 1.70029

	New	Initial release
	New	

Supported Scanners

The Contex LINK software supports the following scanners.

- SD One MF
- IQ FLEX