

Wide Format Scanning and Copying Software

At first start-up you are required to specify a Product Key. The Product Key is located on the distribution media or distributed as a printed or electronic document.
If uninstalling Nextimage, the WIDESystem driver needs to be uninstalled separately.

Contents

[Version Changes](#)

[Supported Operating Systems](#)

[Supported Scanners](#)

[Supported Printers](#)

Version Changes

Changes in version 5.4.4

| | | |
|---------|----------|---|
| | Printers | Added support for: Cannon TX-2100/3100/4100/5210/5310/5410 Canon TZ-5300/30000 HP DesignJet T530/940 HP DesignJet Z6/9 Pro HP PageWide XL 3920/4200/4700/5200/8200 series HP PageWide XL Pro 5200/8200 series |
| NI5-540 | New | Added 'Embedded sRGB profile' option. |
| NI5-543 | Fix | Created TIF files did not follow the word-alignment specification. |
| NI5-544 | Fix | Opening and overwriting BMP file, caused the file to disappear. |

Changes in version 5.4.3

| | | |
|---------|-----|--|
| NI5-494 | New | Support for Océ ColorWave 3600 and 3800, and Océ PlotWave 3000, 3500, 5000, 5500 and 7500. |
| NI5-514 | New | New Support for Epson SC-T34X5 and T54X5 Series. |
| NI5-508 | New | Support for HP DesignJet T1600 ps and T1600dr ps. |
| NI5-520 | New | Support for Windows V4 printer drivers (XPS_PASS). |
| NI5-507 | Fix | Auto size detection for center and right side loaded originals didn't work correct with large originals. |
| NI5-517 | Fix | User-defined media support didn't work with some HP printers. |
| NI5- | Fix | HP DesignJet Z6dr series didn't work. |

| | | |
|-----|--|--|
| 518 | | |
|-----|--|--|

Changes in version 5.4.2

| | | |
|---------|-----|---|
| NI5-503 | Fix | EPSON SC-T34XX/T54XX printers did not work. |
|---------|-----|---|

Changes in version 5.4.1

| | | |
|---------|-----|--|
| | New | Support for the IQ Quattro X 4400 scanner series. |
| NI5-464 | New | Allow manual roll selection on Océ printers. |
| NI5-478 | Fix | Opening 3rd party PDF did not work with latest version of Ghostscript installed. |

Changes in version 5.4

| | | |
|---------|-----|--|
| NI5-310 | New | Reworked remote control of Nextimage via app for iOS and Android devices. New app is called 'Nextimage Remote' and replaces 'Contex AIO'. |
| NI5-401 | Fix | Some print settings could not be saved to presets ('Media destination', 'Folding style', 'Nesting', 'Reverse order' and 'Compensate for margins'). |
| NI5-450 | Fix | User registration text was Japanese while installing with Chinese language. |
| NI5-451 | Fix | Canon printer model not correctly recognized on some systems. |
| NI5-454 | Fix | Using accounting with 'Prompt before every scan' did not allow users to change settings in the pop-up dialog. |
| | Fix | Several updates to Nextimage user interface. |

Changes in version 5.3.5

| | | |
|---------|-----|--|
| NI5-122 | Fix | Pressing OK in Options dialog sometimes resulted in 'Operations failed' message. |
| NI5-417 | Fix | Printing using Océ PlotWave 750 did not work. |
| NI5-418 | Fix | Media selection was not possible on B/W printers. |
| NI5-419 | Fix | Using 'Enhance white', 'Enhance black' or 'Enhance gray' had no effect in viewer. |
| NI5-420 | Fix | User defined media on HP PageWide printers was not working. |
| NI5-422 | Fix | Improvement for top/bottom detection when using 'Full length auto size'. |
| NI5-425 | Fix | Cancelling an Oversize Wizard, could result in crash next time Oversize Wizard was used. |
| NI5-426 | Fix | Some Cancel operations during Set printing resulted in action buttons being wrongly disabled. |
| NI5-427 | Fix | Closing Nextimage to Notification Area and opening again during a Set printing session resulted in unpredictable behavior. |
| NI5- | Fix | Closing Nextimage while opened from TWAIN application, sometimes |

| | | |
|---------|-----|---|
| 428 | | resulted in a crash message. |
| NI5-429 | Fix | First time starting Nextimage from TWAIN after reboot was slow, even when using 'Start with Windows and minimize to Notification Area'. |
| NI5-438 | Fix | Print button did not always work first time after changing auto image adjustments. |

Changes in version 5.3.4

| | | |
|---------|---------|---|
| NI5-416 | Removed | Removed Share task for scanning to cloud services for the SD One+ models. |
|---------|---------|---|

Changes in version 5.3.3

| | | |
|---------|-----|--|
| NI5-313 | Fix | Creating a custom size with scaling caused Nextimage to not start correctly. |
|---------|-----|--|

Changes in version 5.3.2

| | | |
|---------|-----|---|
| NI5-309 | New | Support for HP PageWide XL 3600/3900/4100/4600 Support for HP DesignJet T1600/T2600 |
| NI5-316 | New | Enabled advanced scanner setup for SD One MF. |
| NI5-376 | New | Support for EPSON SC-T34XX/T54XX. |
| NI5-279 | Fix | Improved auto alignment. |
| NI5-313 | Fix | In Chinese language changing units of measure did not always work. |
| NI5-314 | Fix | When scanning fixed length with high dpi the resulting length was smaller than specified. |
| NI5-335 | Fix | Nextimage had problems communicating with printers installed with WSD port. |
| NI5-360 | Fix | 'Center detection' could not be saved in a preset. |
| NI5-362 | Fix | Changing between TM-300 and TX-4000 printer caused Nextimage to crash. |
| NI5-380 | Fix | If enabling Preview before Set printing Nextimage entered a state where no printing was done. |
| | Fix | Several updates to Nextimage user interface. |

Changes in version 5.3.1

| | | |
|--------------------|-----|--|
| NI5-277 NI5-287 | New | Support for RICOH W7100 PS, W8140 PS, W6700SP and MP CW2201SP. |
| NI5-281 NI5-292 | New | Support for Epson SureColor T3470, T5470, T5100 series and T5400 series. |
| NI5-291 | New | 'Full length auto size' option added to support auto size on originals where top and bottom is not same width. |
| NI5- | New | 'Error diffusion' option added for 'Fixed Threshold' to support clean |

| | | |
|--------------------|-----|---|
| 296 | | originals with large fill areas. |
| NI5-47 | Fix | Selection of preset did not work in Share task in Touch mode. |
| NI5-276 | Fix | CLC did not provide optimal result on newer HP printers. |
| NI5-285 NI5-293 | Fix | Oversize had no effect when using auto size on HD Ultra X, HD iFlex or IQ Flex. |
| NI5-290 | Fix | Deleting custom paper size did not work. |
| NI5-303 | Fix | Set printing did not collate as explained in help. |
| NI5-305 | Fix | Creating PNG and JPEG2000 files did not work if filename had non-ANSI characters. |
| | Fix | Several updates to Nextimage user interface. |

Changes in version 5.3

| | | |
|---------|-----|---|
| NI5-167 | New | 'Manual scale correction' added to allow users to manually adjust horizontal scaling. Only supported on HD Ultra X scanners. |
| NI5-169 | New | 'Manual load' option added to support scanning of hard to load originals. Only supported on HD Ultra X scanners. |
| NI5-209 | New | Faster LZW compression. |
| NI5-123 | Fix | Opening some 3 rd party PDF files caused Nextimage to crash. |
| NI5-186 | Fix | When doing autosize scans on HD Ultra X scanners, 'Top offset' had no effect. |
| NI5-229 | Fix | Updated driver for HP DesignJet T1700, T1708, Z6 and Z9. This fixes issues with multipage printing. |
| NI5-239 | Fix | When scanning with 'Load position' set to Right on IQ FLEX, the scan was done at center. |
| NI5-246 | Fix | Some GUI elements were not displayed correctly on older versions of Windows. |
| | Fix | Several updates to both Nextimage and iCopy user interfaces. Including many fixes for 4K displays. |

Changes in version 5.2.3

| | | |
|---------|-----|--|
| NI5-174 | New | Support for HP PageWide XL 5100 and 6000 series. |
| NI5-176 | New | Support for Canon Canon TM-200, TM-205, TM-300, TM-305, TM-5200, TM-5205, TM-5300 and TM-5305. |
| NI5-19 | Fix | Trying to print multiple copies to the Canon TX printer series caused an error. |
| NI5-25 | Fix | Month field in filename did not work. |
| | | |

| | | |
|---------|-----|--|
| NI5-26 | Fix | Printing to USB-connected Canon printers did not work. |
| NI5-35 | Fix | Sometimes extra data at right side of the scan was added. |
| NI5-119 | Fix | Saving to DWF with non-ASCII characters in file name resulted in an error. |
| | Fix | Several updates to both Nextimage and iCopy user interfaces. |

Changes in version 5.2.2

| | | |
|---------|-----|---|
| NI5-168 | New | Support for Océ ColorWave 3500, 3700 and 9000 |
| NI5-36 | New | Support for Océ PlotWave 345, 365, 450 and 550 |
| NI5-29 | New | Improved handling of Extended Thickness scanning for HD Ultra X |

Changes in version 5.2.1

| | | |
|---------|-----|--|
| NEX-588 | Fix | When scanning using iOS app, the Nextimage messages was not shown in iOS app. |
| NEX-688 | Fix | If converting image from color to grayscale a black line appeared at right edge. |

Changes in version 5.2

| | | |
|---------|-----|---|
| | New | Support for the HD Ultra X 6000 scanner series. |
| | New | Remote control Nextimage via 'Contex AIO' app for iOS and Android devices. Only supported on HD Ultra X 6000 scanners. |
| NEX-9 | New | 'Auto size' to 'Any Size' without doing a prescan first. Only supported on HD Ultra X 6000 scanners. |
| NEX-24 | New | Help user to find email addresses, by searching the Windows AD. |
| NEX-53 | New | Support for BigTiff (TIFF variant with support for files >4GB). |
| NEX-410 | New | Manual roll selection for printer medias implemented. |
| NEX-497 | New | PDF larger than 200" without inserting page breaks. |
| NEX-315 | Fix | Scanning with negative 'Stitching' value(s) did not work. |
| NEX-625 | Fix | Color picker and Crop did not work using a touch screen. |
| NEX-628 | Fix | Flatbed oversize scans to a multipage document did not work. |
| | Fix | Several updates to user interface. |

Changes in version 5.1.4

| | | |
|----------------|-----|------------------------------------|
| 35717 35944 | New | Support for HP DesignJet Z6 and Z9 |
|----------------|-----|------------------------------------|

| | | |
|-------|-----|---|
| 35854 | New | Support for HP DesignJet Z6610 and Z6810 |
| 36029 | New | Support for HP DesignJet T1708 |
| 35506 | New | TWAINDSM updated to v 2.3.0 |
| 35782 | New | Faster Descreening option |
| 35492 | Fix | TWAIN implementation not compatible with Pixedit |
| 35579 | Fix | Printers included in presets were not selected |
| 36012 | Fix | Canvas Matte media type was not supported for Canon iPF9100 |
| 35994 | Fix | PDF/A compatibility was not correct according to the standard |

Changes in version 5.1.3

| | | |
|-------------------------|-----|--|
| 34745 | New | Support for HP DesignJet T1700, T1700 Postscript, T1700dr, T1700dr Postscript. |
| 35300 | New | Support for Canon PRO-6000. |
| 35368 | Fix | BW Group3 compression made horizontal lines in file. |
| 35367 33758 33066 | Fix | Several TWAIN issues solved. |
| 34443 | Fix | Long PDF files (>200") did not open/print correctly in the Adobe Acrobat reader. |
| 35311 | Fix | Overwrite file name did not update correct if file already existed. |
| 35208 | Fix | A renamed file would incorrectly be saved in the default Windows folder. |

Changes in version 5.1.2

| | | |
|-------|-----|--|
| 34950 | New | Support for Canon TX-2000, Canon TX-3000, Canon TX-4000, Canon TX-5200, Canon TX-5300 and Canon TX-5400. |
| 35114 | Fix | Sometimes the F2 shortcut (Scan) did not work. |
| 35009 | Fix | Use of One-Touch keys for scan and copy gave incorrect user message |
| 34424 | Fix | Improved bidirectional communication for some Océ printer models |
| 35097 | Fix | Use of custom media types for HP printer models did not work. |
| 35180 | Fix | Auto file naming sometimes did not have effect. |
| 35185 | Fix | 3 rd party JPEG files with EXif properties were incorrectly opened in 300dpi |

Changes in version 5.1.1

| | | |
|-------|-----|---|
| 34285 | Fix | Pinch zoom did not work. |
| 34574 | Fix | Saving an opened PDF file resulted in changed resolution. |
| | Fix | Several updates to user interface, most related to book scanning. |

Changes in version 5.1

| | | |
|-------|-----|---|
| | New | Support for the IQ FLEX scanner. Including support for book scanning. |
| 32699 | New | 'Content alignment' option on HP PageWide printer series to allow better support for folders. |
| 33375 | New | Improved auto size detection on HD iFLEX. |

| | | |
|-------|-----|--|
| 34349 | New | Support both rolls on the Epson SC-TxxxD printer series. |
| 34363 | Fix | Support SD4400 scanner series. |
| 34370 | Fix | Improved bi-directional support on Océ printers. |
| | Fix | Several updates to user interface. |

Changes in version 5.0.2

| | | |
|-------|-----|---|
| 29871 | New | Crop panel now available in Scan and Copy tasks. The panel is now placed under Image Adjustment panel. The previously location in File task was under the Input File panel. |
| 33110 | New | Updated dialogs to use the new color scheme. |
| 33478 | New | The media database will be updated for some HP printers when new medias are introduced in the printer firmware. |
| 33679 | New | Bi-directional communication is now supported for Océ ColorWave 910. |
| 33154 | New | Support for the IQ Quattro 3600 scanner series. |
| 33813 | New | Improved support for Canon PRO printers without bi-directional communication. |
| 32244 | Fix | Generation of PDF file to destination with insufficient free storage failed. |
| 33291 | Fix | Auto length (with fixed width) did not work after a restart. |
| 33525 | Fix | Browsing for destination in File task did not update file type. |
| 33586 | Fix | Improved bi-directional communication with HP Designjet T930, T1530 and T2530. |
| 33610 | Fix | The measure line tool disappeared when zooming. |
| 33624 | Fix | Changes to B/W Point in Adaptive Threshold had no effect. |
| 33763 | Fix | IQ 2400/4400 series scanners were not found. |
| 33775 | Fix | Changing Registered User information did not have effect until after a restart. |
| 33928 | Fix | 'Clear image view after' timeout message could happen during scanning. |
| 33929 | Fix | Printing multipage files didn't work. |
| | Fix | Several updates to user interface. |

Changes in version 5.0.1

| | | |
|-------|-----|--|
| 30239 | New | Nextimage registered in Windows firewall during installation. |
| 33260 | New | Faster non 90-degree rotations. |
| 33380 | New | Opened file size now showed in metrics (inch/cm/mm) as well as pixels. |
| 33441 | New | Registered owner can be changed from within Nextimage using the 'Product Registration/Upgrade' dialog. |
| 33495 | New | Turkish on-screen keyboard. |
| 33575 | New | Paper size added to accounting log if scanning fixed size. |
| 33577 | New | Support for SD One MF 24/36/44 scanners. |
| 32648 | Fix | When selecting save destination in File task then file format was not changed. |
| | | |

| | | |
|-------------------------|-----|---|
| 32692 | Fix | Using a printer without connection sometimes resulted in 'No Printer Communication' dialog that kept appearing when closed. |
| 32749 | Fix | Saving Resize options to presets did not work. |
| 32779 | Fix | 'Reset All Settings' did not work in File task. |
| 33028 | Fix | Not possible to save custom output Scale percentage. |
| 33035 33306 33308 | Fix | Selection/deselection of color pickers did not always work. |
| 33269 | Fix | Free edition did not work correctly when started first time. |
| 33300 | Fix | Measure line often showed 1pixel instead of the actual distance. |
| 33379 | Fix | Using Crop panel in File task had did not update selected area in viewer. |
| 33395 | Fix | Using printer without connection sometimes made it impossible to select another printer. |
| 33477 | Fix | B&W PDF files from version 4.5 could not be opened. |
| 33492 | Fix | Destination email addresses could not be saved. |
| 33572 | Fix | Changing file format after scanning sometimes caused Update button to be disabled. |
| 33596 | Fix | Generated PDF sometimes empty when opened using Adobe viewer due to pages exceeding 200 inches. |
| 33609 | Fix | Resolution sometimes reduced to 800dpi when starting Nextimage. |
| | Fix | Several updates to user interface. |

Changes in version 5.0

| | | |
|-------|-----|--|
| 30432 | New | Converted to 64 bit application. |
| 31949 | New | New graphical design. |
| 32265 | New | Getting Started Guide in Help. |
| 31950 | New | Collated Set copying with nesting and reverse order options. |
| 31953 | New | Lossless color compression option for PDF. |
| 31853 | New | New smoothen algorithm. |
| 31951 | New | Split TIFF files when exceeding file limits. |
| 31952 | New | Split PDF into multiple pages when exceeding page limit of 200 inches. |
| 33212 | New | Installation requires End User registration/validation. |
| 33220 | New | Auto Update no longer requires End User registration. |
| 33235 | Fix | Scanning/saving with 90-degree rotation was very slow. |

Supported Operating Systems

- Windows Server 2019 (Standard Edition), 64-bit
- Windows 8.1 (Enterprise) 32-bit
- Windows 8.1 (Enterprise) 64-bit
- Windows 10 (Enterprise) 32-bit
- Windows 10 (Enterprise) 64-bit

Supported Scanners

| Series | Specific Models | | |
|-----------------|--|--------------------------|-----------------------|
| CG | CG710 | CG810 | |
| IQ | IQ 2420 IQ 4420 | IQ 2490 IQ 4450 | IQ 4490 |
| IQ FLEX | IQ FLEX | | |
| IQ Quattro | IQ Quattro 2420 | IQ Quattro 2450 | IQ Quattro 2490u |
| | IQ Quattro 2490 | | |
| | IQ Quattro 3620 | IQ Quattro 3650 | IQ Quattro 3690u |
| | IQ Quattro 3690 | | |
| | IQ Quattro 4420 | IQ Quattro 4450 | IQ Quattro 4490u |
| | IQ Quattro 4490 | | |
| IQ Quattro X | IQ Quattro X 4420 | IQ Quattro X 4450 | IQ Quattro X 4490 |
| SD One | SD One 24 SD One 36 | SD One 24+ SD One 36+ | |
| SD One MF | SD One MF 24 SD One MF 36 SD One MF 44 | | |
| SD | SD3610 SD3619 SD3690+ | SD3610+ SD3620 | SD3615 MFP SD3650+ |
| HD iFLEX | HD iFLEX | HD iFLEXu | |
| HD Ultra | HD Ultra 3610 | HD Ultra 3610+ | HD Ultra 3610i |
| | HD Ultra 3610i+ | HD Ultra 3630 | HD Ultra 3630+ |
| | HD Ultra 3630i | HD Ultra 3630i+ | HD Ultra 3650+ |
| | HD Ultra 3650i+ | HD Ultra 3690i+ | |
| | HD Ultra i3610s | HD Ultra i3620s | HD Ultra i3650s |
| | HD Ultra i3690s | | |
| | HD Ultra 4210 | HD Ultra 4210+ | HD Ultra 4210i |
| | HD Ultra 4210i+ | HD Ultra 4230 | HD Ultra 4230+ |
| | HD Ultra 4230i | HD Ultra 4230i+ | HD Ultra 4250+ |
| | HD Ultra 4250i+ | HD Ultra 4290i+ | |
| | HD Ultra i4210s | HD Ultra i4220s | HD Ultra i4250s |
| | HD Ultra i4290s | | |
| | HD Ultra X | HD Ultra X 3610 | HD Ultra X 3620 |
| HD Ultra X 3690 | | | |
| HD Ultra X 4210 | | HD Ultra X 4220 | HD Ultra X 4250 |
| HD Ultra X 4290 | | | |
| HD Ultra X 6010 | | HD Ultra X 6020 | HD Ultra X 6050 |
| HD Ultra X 6090 | | | |
| HD54 | HD5430 HD5450+ | HD5430+ | HD5450 |