

Wide Format Scanning and Copying Software

At first start-up you are required to specify a Product Key. The Product Key is located on the distribution media or distributed as a printed or electronic document.
If uninstalling Nextimage, the WIDEsystem driver needs to be uninstalled separately.

Contents

[Version Changes](#)

[Supported Operating Systems](#)

[Supported Scanners](#)

[Supported Printers](#)

Version Changes

Changes in version 5.4.7		
NI5-584	Fix	Sometimes the length of the embedded JPG file in PDF file format was incorrect
NI5-574	Printers	Added support for: Epson SureColor SC-P7500/7530/7540/7550/7560/7570/7580 Epson SureColor SC-P9500/9530/9540/9550/9560/9570/9580
NI5-511	New	Option to collapse/expand yellow page counter sticker in lower-right corner
NI5-534 NI5-558	Fix	Space keyboard shortcut did not work
NI5-537	Fix	Using crop and/or mirror in opened multipage file had no effect when saving
NI5-548	Fix	Changing file format between TIFF and PDF, resulted in disabling of Batch button
NI5-569	Fix	Using incremental counter with multipage and batch enabled, resulted in skip of numbers
NI5-576	Fix	Writing invalid tag in filename, resulted in 'Reset All Settings' not working
NI5-577	Fix	Selecting WPS PDF printer caused error
Changes in version 5.4.6		
NI5-563	Scanners	Added support for: HD Ultra X 42xx and HD Ultra X 60xx with CBV camera board

NI5-560	Printers	<p>Added support for:</p> <p>Epson SureColor SC-P6500/P8500 Epson SureColor SC-T3700/3730/3740/3750/3760/3770/3780/3790 Epson SureColor SC-T5700/5730/5740/5750/5760/5770/5780/5790 Epson SureColor SC-T7700/7730/7740/7750/7760/7770/7780/7790 HP DesignJet T630</p>
NI5-554	Fix	HP printers with PDF in their name did not use our application printer driver
NI5-561	Fix	HP DesignJet T520 printer did not function correctly
NI5-562	Fix	Scanning to JPG with oversize scanning on IQ Flex resulted in no output file

Changes in version 5.4.4

	Printers	<p>Added support for:</p> <p>Cannon TX-2100/3100/4100/5210/5310/5410 Canon TZ-5300/30000 HP DesignJet T530/940 HP DesignJet Z6/9 Pro HP PageWide XL 3920/4200/4700/5200/8200 series HP PageWide XL Pro 5200/8200 series</p>
NI5-540	New	Added 'Embedded sRGB profile' option.
NI5-543	Fix	Created TIF files did not follow the word-alignment specification.
NI5-544	Fix	Opening and overwriting BMP file, caused the file to disappear.

Changes in version 5.4.3

NI5-494	New	Support for Océ ColorWave 3600 and 3800, and Océ PlotWave 3000, 3500, 5000, 5500 and 7500.
NI5-514	New	New Support for Epson SC-T34X5 and T54X5 Series.
NI5-508	New	Support for HP DesignJet T1600 ps and T1600dr ps.
NI5-520	New	Support for Windows V4 printer drivers (XPS_PASS).
NI5-507	Fix	Auto size detection for center and right side loaded originals didn't work correct with large originals.
NI5-517	Fix	User-defined media support didn't work with some HP printers.
NI5-518	Fix	HP DesignJet Z6dr series didn't work.

Changes in version 5.4.2

NI5-503	Fix	EPSON SC-T34XX/T54XX printers did not work.
---------	-----	---

Changes in version 5.4.1

	New	Support for the IQ Quattro X 4400 scanner series.
NI5-464	New	Allow manual roll selection on Océ printers.
NI5-478	Fix	Opening 3rd party PDF did not work with latest version of Ghostscript installed.

Changes in version 5.4

NI5-310	New	Reworked remote control of Nextimage via app for iOS and Android devices. New app is called 'Nextimage Remote' and replaces 'Contex AIO'.
NI5-401	Fix	Some print settings could not be saved to presets ('Media destination', 'Folding style', 'Nesting', 'Reverse order' and 'Compensate for margins').
NI5-450	Fix	User registration text was Japanese while installing with Chinese language.
NI5-451	Fix	Canon printer model not correctly recognized on some systems.
NI5-454	Fix	Using accounting with 'Prompt before every scan' did not allow users to change settings in the pop-up dialog.
	Fix	Several updates to Nextimage user interface.

Changes in version 5.3.5

NI5-122	Fix	Pressing OK in Options dialog sometimes resulted in 'Operations failed' message.
NI5-417	Fix	Printing using Océ PlotWave 750 did not work.
NI5-418	Fix	Media selection was not possible on B/W printers.
NI5-419	Fix	Using 'Enhance white', 'Enhance black' or 'Enhance gray' had no effect in viewer.
NI5-420	Fix	User defined media on HP PageWide printers was not working.
NI5-422	Fix	Improvement for top/bottom detection when using 'Full length auto size'.
NI5-425	Fix	Cancelling an Oversize Wizard, could result in crash next time Oversize Wizard was used.
NI5-426	Fix	Some Cancel operations during Set printing resulted in action buttons being wrongly disabled.
NI5-427	Fix	Closing Nextimage to Notification Area and opening again during a Set printing session resulted in unpredictable behavior.
NI5-428	Fix	Closing Nextimage while opened from TWAIN application, sometimes resulted in a crash message.

NI5-429	Fix	First time starting Nextimage from TWAIN after reboot was slow, even when using 'Start with Windows and minimize to Notification Area'.
NI5-438	Fix	Print button did not always work first time after changing auto image adjustments.
Changes in version 5.3.4		
NI5-416	Removed	Removed Share task for scanning to cloud services for the SD One+ models.
Changes in version 5.3.3		
NI5-313	Fix	Creating a custom size with scaling caused Nextimage to not start correctly.
Changes in version 5.3.2		
NI5-309	New	Support for HP PageWide XL 3600/3900/4100/4600 Support for HP DesignJet T1600/T2600
NI5-316	New	Enabled advanced scanner setup for SD One MF.
NI5-376	New	Support for EPSON SC-T34XX/T54XX.
NI5-279	Fix	Improved auto alignment.
NI5-313	Fix	In Chinese language changing units of measure did not always work.
NI5-314	Fix	When scanning fixed length with high dpi the resulting length was smaller than specified.
NI5-335	Fix	Nextimage had problems communicating with printers installed with WSD port.
NI5-360	Fix	'Center detection' could not be saved in a preset.
NI5-362	Fix	Changing between TM-300 and TX-4000 printer caused Nextimage to crash.
NI5-380	Fix	If enabling Preview before Set printing Nextimage entered a state where no printing was done.
	Fix	Several updates to Nextimage user interface.
Changes in version 5.3.1		
NI5-277 NI5-287	New	Support for RICOH W7100 PS, W8140 PS, W6700SP and MP CW2201SP.
NI5-281 NI5-292	New	Support for Epson SureColor T3470, T5470, T5100 series and T5400 series.
NI5-291	New	'Full length auto size' option added to support auto size on originals where top and bottom is not same width.
NI5-296	New	'Error diffusion' option added for 'Fixed Threshold' to support clean originals with large fill areas.

NI5-47	Fix	Selection of preset did not work in Share task in Touch mode.
NI5-276	Fix	CLC did not provide optimal result on newer HP printers.
NI5-285 NI5-293	Fix	Oversize had no effect when using auto size on HD Ultra X, HD iFlex or IQ Flex.
NI5-290	Fix	Deleting custom paper size did not work.
NI5-303	Fix	Set printing did not collate as explained in help.
NI5-305	Fix	Creating PNG and JPEG2000 files did not work if filename had non-ANSI characters.
	Fix	Several updates to Nextimage user interface.

Changes in version 5.3

NI5-167	New	'Manual scale correction' added to allow users to manually adjust horizontal scaling. Only supported on HD Ultra X scanners.
NI5-169	New	'Manual load' option added to support scanning of hard to load originals. Only supported on HD Ultra X scanners.
NI5-209	New	Faster LZW compression.
NI5-123	Fix	Opening some 3 rd party PDF files caused Nextimage to crash.
NI5-186	Fix	When doing autosize scans on HD Ultra X scanners, 'Top offset' had no effect.
NI5-229	Fix	Updated driver for HP DesignJet T1700, T1708, Z6 and Z9. This fixes issues with multipage printing.
NI5-239	Fix	When scanning with 'Load position' set to Right on IQ FLEX, the scan was done at center.
NI5-246	Fix	Some GUI elements were not displayed correctly on older versions of Windows.
	Fix	Several updates to both Nextimage and iCopy user interfaces. Including many fixes for 4K displays.

Changes in version 5.2.3

NI5-174	New	Support for HP PageWide XL 5100 and 6000 series.
NI5-176	New	Support for Canon Canon TM-200, TM-205, TM-300, TM-305, TM-5200, TM-5205, TM-5300 and TM-5305.
NI5-19	Fix	Trying to print multiple copies to the Canon TX printer series caused an error.
NI5-25	Fix	Month field in filename did not work.

NI5-26	Fix	Printing to USB-connected Canon printers did not work.
NI5-35	Fix	Sometimes extra data at right side of the scan was added.
NI5-119	Fix	Saving to DWF with non-ASCII characters in file name resulted in an error.
	Fix	Several updates to both Nextimage and iCopy user interfaces.

Changes in version 5.2.2

NI5-168	New	Support for Océ ColorWave 3500, 3700 and 9000
NI5-36	New	Support for Océ PlotWave 345, 365, 450 and 550
NI5-29	New	Improved handling of Extended Thickness scanning for HD Ultra X

Changes in version 5.2.1

NEX-588	Fix	When scanning using iOS app, the Nextimage messages was not shown in iOS app.
NEX-688	Fix	If converting image from color to grayscale a black line appeared at right edge.

Changes in version 5.2

	New	Support for the HD Ultra X 6000 scanner series.
	New	Remote control Nextimage via 'Contex AIO' app for iOS and Android devices. Only supported on HD Ultra X 6000 scanners.
NEX-9	New	'Auto size' to 'Any Size' without doing a prescan first. Only supported on HD Ultra X 6000 scanners.
NEX-24	New	Help user to find email addresses, by searching the Windows AD.
NEX-53	New	Support for BigTiff (TIFF variant with support for files >4GB).
NEX-410	New	Manual roll selection for printer medias implemented.
NEX-497	New	PDF larger than 200" without inserting page breaks.
NEX-315	Fix	Scanning with negative 'Stitching' value(s) did not work.
NEX-625	Fix	Color picker and Crop did not work using a touch screen.
NEX-628	Fix	Flatbed oversize scans to a multipage document did not work.
	Fix	Several updates to user interface.

Changes in version 5.1.4

37717 35944	New	Support for HP DesignJet Z6 and Z9
----------------	-----	------------------------------------

35854	New	Support for HP DesignJet Z6610 and Z6810
36029	New	Support for HP DesignJet T1708
35506	New	TWAINDSM updated to v 2.3.0
37782	New	Faster Descreening option
35492	Fix	TWAIN implementation not compatible with Pixedit
35779	Fix	Printers included in presets were not selected
36012	Fix	Canvas Matte media type was not supported for Canon iPF9100
35994	Fix	PDF/A compatibility was not correct according to the standard

Changes in version 5.1.3

34745	New	Support for HP DesignJet T1700, T1700 Postscript, T1700dr, T1700dr Postscript.
35300	New	Support for Canon PRO-6000.
35368	Fix	BW Group3 compression made horizontal lines in file.
35367 33758 33066	Fix	Several TWAIN issues solved.
34443	Fix	Long PDF files (>200") did not open/print correctly in the Adobe Acrobat reader.
35311	Fix	Overwrite file name did not update correct if file already existed.
35208	Fix	A renamed file would incorrectly be saved in the default Windows folder.

Changes in version 5.1.2

34950	New	Support for Canon TX-2000, Canon TX-3000, Canon TX-4000, Canon TX-5200, Canon TX-5300 and Canon TX-5400.
35114	Fix	Sometimes the F2 shortcut (Scan) did not work.
35009	Fix	Use of One-Touch keys for scan and copy gave incorrect user message
34424	Fix	Improved bidirectional communication for some Océ printer models
35097	Fix	Use of custom media types for HP printer models did not work.
35180	Fix	Auto file naming sometimes did not have effect.
35185	Fix	3 rd party JPEG files with EXif properties were incorrectly opened in 300dpi

Changes in version 5.1.1

34285	Fix	Pinch zoom did not work.
34774	Fix	Saving an opened PDF file resulted in changed resolution.
	Fix	Several updates to user interface, most related to book scanning.

Changes in version 5.1

	New	Support for the IQ FLEX scanner. Including support for book scanning.
32699	New	'Content alignment' option on HP PageWide printer series to allow better support for folders.
33375	New	Improved auto size detection on HD iFLEX.
34349	New	Support both rolls on the Epson SC-TxxxD printer series.
34363	Fix	Support SD4400 scanner series.
34370	Fix	Improved bi-directional support on Océ printers.
	Fix	Several updates to user interface.

Changes in version 5.0.2

29871	New	Crop panel now available in Scan and Copy tasks. The panel is now placed under Image Adjustment panel. The previously location in File task was under the Input File panel.
33110	New	Updated dialogs to use the new color scheme.
33478	New	The media database will be updated for some HP printers when new medias are introduced in the printer firmware.
33679	New	Bi-directional communication is now supported for Océ ColorWave 910.
33154	New	Support for the IQ Quattro 3600 scanner series.
33813	New	Improved support for Canon PRO printers without bi-directional communication.
32244	Fix	Generation of PDF file to destination with insufficient free storage failed.
33291	Fix	Auto length (with fixed width) did not work after a restart.
33525	Fix	Browsing for destination in File task did not update file type.
33586	Fix	Improved bi-directional communication with HP Designjet T930, T1530 and T2530.
33610	Fix	The measure line tool disappeared when zooming.
33624	Fix	Changes to B/W Point in Adaptive Threshold had no effect.
33763	Fix	IQ 2400/4400 series scanners were not found.
33775	Fix	Changing Registered User information did not have effect until after a restart.
33928	Fix	'Clear image view after' timeout message could happen during scanning.
33929	Fix	Printing multipage files didn't work.
	Fix	Several updates to user interface.

Changes in version 5.0.1

30239	New	Nextimage registered in Windows firewall during installation.
33260	New	Faster non 90-degree rotations.

33380	New	Opened file size now showed in metrics (inch/cm/mm) as well as pixels.
33441	New	Registered owner can be changed from within Nextimage using the 'Product Registration/Upgrade' dialog.
33495	New	Turkish on-screen keyboard.
33775	New	Paper size added to accounting log if scanning fixed size.
33777	New	Support for SD One MF 24/36/44 scanners.
32648	Fix	When selecting save destination in File task then file format was not changed.
32692	Fix	Using a printer without connection sometimes resulted in 'No Printer Communication' dialog that kept appearing when closed.
32749	Fix	Saving Resize options to presets did not work.
32779	Fix	'Reset All Settings' did not work in File task.
33028	Fix	Not possible to save custom output Scale percentage.
33035 33306 33308	Fix	Selection/deselection of color pickers did not always work.
33269	Fix	Free edition did not work correctly when started first time.
33300	Fix	Measure line often showed 1pixel instead of the actual distance.
33379	Fix	Using Crop panel in File task had did not update selected area in viewer.
33395	Fix	Using printer without connection sometimes made it impossible to select another printer.
33477	Fix	B&W PDF files from version 4.5 could not be opened.
33492	Fix	Destination email addresses could not be saved.
33772	Fix	Changing file format after scanning sometimes caused Update button to be disabled.
33596	Fix	Generated PDF sometimes empty when opened using Adobe viewer due to pages exceeding 200 inches.
33609	Fix	Resolution sometimes reduced to 800dpi when starting Nextimage.
	Fix	Several updates to user interface.

Changes in version 5.0

30432	New	Converted to 64 bit application.
31949	New	New graphical design.
32265	New	Getting Started Guide in Help.
31950	New	Collated Set copying with nesting and reverse order options.
31953	New	Lossless color compression option for PDF.
31853	New	New smoothen algorithm.
31951	New	Split TIFF files when exceeding file limits.

31952	New	Split PDF into multiple pages when exceeding page limit of 200 inches.
33212	New	Installation requires End User registration/validation.
33220	New	Auto Update no longer requires End User registration.
33235	Fix	Scanning/saving with 90-degree rotation was very slow.

Supported Operating Systems

- Windows Server 2022 (Standard Edition)
- Windows 10 (Enterprise)
- Windows 11 (Enterprise)

Supported Scanners

Series	Specific Models
CG	<ul style="list-style-type: none"> • CG710 • CG810
IQ	<ul style="list-style-type: none"> • IQ 2420 • IQ 2490 • IQ 4420 • IQ 4450 • IQ 4490
IQ FLEX	<ul style="list-style-type: none"> • IQ FLEX
IQ Quattro	<ul style="list-style-type: none"> • IQ Quattro 2420 • IQ Quattro 2450 • IQ Quattro 2490u • IQ Quattro 2490 • IQ Quattro 3620 • IQ Quattro 3650 • IQ Quattro 3690u • IQ Quattro 3690 • IQ Quattro 4420 • IQ Quattro 4450 • IQ Quattro 4490u • IQ Quattro 4490
IQ Quattro X	<ul style="list-style-type: none"> • IQ Quattro X 4420 • IQ Quattro X 4450 • IQ Quattro X 4490
SD One	<ul style="list-style-type: none"> • SD One 24 • SD One 24+ • SD One 36 • SD One 36+
SD One MF	<ul style="list-style-type: none"> • SD One MF 24 • SD One MF 36 • SD One MF 44
SD	<ul style="list-style-type: none"> • SD3610 • SD3610+ • SD3615 MFP

	<ul style="list-style-type: none"> • SD3619 • SD3620 • SD3650+ • SD3690+
HD iFLEX	<ul style="list-style-type: none"> • HD iFLEX • HD iFLEXu
HD Ultra	<ul style="list-style-type: none"> • HD Ultra 3610 • HD Ultra 3610+ • HD Ultra 3610i • HD Ultra 3610i+ • HD Ultra 3630 • HD Ultra 3630+ • HD Ultra 3630i • HD Ultra 3630i+ • HD Ultra 3650+ • HD Ultra 3650i+ • HD Ultra 3690i+ • HD Ultra i3610s • HD Ultra i3620s • HD Ultra i3650s • HD Ultra i3690s • HD Ultra 4210 • HD Ultra 4210+ • HD Ultra 4210i • HD Ultra 4210i+ • HD Ultra 4230 • HD Ultra 4230+ • HD Ultra 4230i • HD Ultra 4230i+ • HD Ultra 4250+ • HD Ultra 4250i+ • HD Ultra 4290i+ • HD Ultra i4210s • HD Ultra i4220s • HD Ultra i4250s • HD Ultra i4290s
HD Ultra X	<ul style="list-style-type: none"> • HD Ultra X 3610 • HD Ultra X 3620 • HD Ultra X 3650 • HD Ultra X 3690 • HD Ultra X 4210 • HD Ultra X 4220 • HD Ultra X 4250 • HD Ultra X 4290 • HD Ultra X 6010 • HD Ultra X 6020 • HD Ultra X 6050 • HD Ultra X 6090
HD54	<ul style="list-style-type: none"> • HD5430 • HD5430+ • HD5450 • HD5450+