Wide Format Scanning and Copying Software

At first start-up you are required to specify a Product Key. The Product Key is located on the distribution media or distributed as a printed or electronic document.

If uninstalling Nextimage, the WIDEsystem driver needs to be uninstalled separately.

Contents

Version Changes
Supported Operating Systems
Supported Scanners
Supported Printers

Version Changes

Changes in version 4.4.3

| 31271 | New | Support for EPSON SC-T3200D, SC-T3250, SC-T3250D, SC-T3270, SC-T3270D, SC-T5250, SC-T5250D, SC-T5270D, SC-T7250, SC-T7250D, SC-T7270D. |
|-------|-----|--|
| 31342 | Fix | Missing texts under icons in image tool bar. |
| 31390 | Fix | For HP PageWide XL the Print Quality did not select the correct options. |
| 31544 | Fix | Auto White Point / Black Point gave wrong result when used in combination with sharpen. |
| 31563 | Fix | Unable to select scan resolution in Touch Mode at a specific panel width. |
| | Fix | Several updates to user interface, translations and help. |

Changes in version 4.4.2

| 30931 | New | Support for Epson Stylus Pro 7710, 7880, 7880C, 7890, 7900, 7910, |
|-------|-----|---|
| 31218 | | 9710, 9880, 9880C, 9890, 9900, 9910, 11880, 11880C and Epson |
| | | SureColor SC-P6000, SC-P7000, SC-P8000, SC-P9000. |

Changes in version 4.4.1

| 30621 | New | Support for HP PageWide XL 4000/4500/5000/8000. |
|-------|-----|--|
| 30687 | New | Support for Océ ColorWave 500/700/810/900/910. |
| | | Support for Océ PlotWave 340/360/500. |
| 30866 | New | Support for HP Designjet T930/T1530/T2530. |
| 30867 | New | Support for HP Designjet T730/T830 MFP. |
| 30669 | New | Improved reaction time when cancelling a scan. |
| 30696 | New | Improved reaction time when starting a scan. |
| 30799 | New | Media control buttons to move original in SD One scanner. |
| 30620 | Fix | Black and white point did not work correctly when using Adaptive |
| | | Threshold. |

| 30639 | Fix | Error message could appear during shut down of application. |
|-------|-----|---|
| 30869 | Fix | Switching Task could take very long time. |
| 30822 | Fix | Application crash when starting a scan while having extension-less files in the Windows Color folder. |
| 30797 | Fix | Missing support for legacy scanner HD5430. |

Changes in version 4.4

| 30395 | New | Support for Canon iPF830/840/850 and iPF831/841/851. |
|-------|-----|--|
| 29872 | Fix | When scanning an original smaller than a selected fixed size, only the size |
| | | of the original was indicated in the viewer and subsequently saved to file. |
| 30077 | Fix | Multipage TIF could result in invalid files when re-saving or deleting the |
| 30245 | | last scan. |
| 30086 | Fix | Using French on-screen keyboard (in Touch Screen mode) could result in |
| | | the numeric on-screen keyboard not working. |
| 30181 | Fix | The Output file option 'If file exist' was sometimes automatically set to |
| | | 'Rename'. |
| 30181 | Fix | When inserting a counter field larger than 1 in the file name in batch mode, |
| | | could cause wrong naming of files. |
| 30295 | Fix | The 'Delete Last Scan' function did not decrement file name counter field |
| | | used while in batch mode. |
| | | Several user interface corrections |

Changes in version 4.3.2

| New | 'Delete Last Scan' button added in Output File panel to ease rescanning to |
|-----|---|
| | the same filename. |
| New | 'Repro Edition Trial' option added for SD One scanners. |
| New | Improved reaction time between pressing 'Scan' button and start of scan. |
| New | Improved auto size detection on iFLEX scanner. |
| Fix | Gamma was sometimes changed to 5.0 when not using period as decimal |
| | separator. |
| Fix | For IQ Quattro scanners the 'Light Source' option was sometimes hidden. |
| Fix | Scanning 'B&W Threshold' or 'B&W Adaptive' via TWAIN sometimes |
| | caused error. |
| Fix | Image on screen was shown with the printer's color calibration when |
| | copying using Closed Loop Calibration (CLC). |
| Fix | Installation did not always ask for admin rights even though they are |
| | required. |
| Fix | For SD One scanners two scans were made if double clicking the 'Scan' |
| | button in the Share task. |
| Fix | For SD One scanners clicking the 'Save' button in the Share task while |
| | still transferring an image to the cloud resulted in an upload error. |
| Fix | Using the 'Descreening' resolution type on iFLEX together with auto size |
| | resulted in a large white area added to file. |
| Fix | Using 'Mirror' and 'Indexed Color' sometimes resulted in a vertical line in |
| | the middle of the scan. |
| Fix | Unified installation of Nextimage and the WIDEsystem driver did not ask |
| | for reboot when launched from USB key. |
| Fix | When printing to HP Designjet T7100 the active roll was used instead of |
| | the media selected. |
| | New New New Fix |

| Fix Several user interface corrections. |
|---|
|---|

Changes in version 4.3.1

| 29936 | Fix | Various problems in Nextimage TWAIN driver. |
|-------|-----|---|
| 29989 | | |

Changes in version 4.3

| 28725 | New | Unified installation of Nextimage and the WIDEsystem driver (when the |
|-------|-----|--|
| | | WIDEsystem package is placed in a WS subfolder). The two applications |
| | | need to be individually uninstalled e.g. if downgrading an installation. |
| 29639 | New | Automatic software update notification (for selected scanner models). |
| 29665 | New | Free-edition for SD One scanners with simplified Scan task and new Share |
| | | task for scanning to cloud services. |
| 29666 | New | Improved auto black/white point detection. |
| 29681 | New | Support for Canon iPF670/671/770/771. |
| 29720 | New | Support for HP Designjet T7200/T7200PS. |
| 29641 | Fix | Preview using HP T7100 printer resulted in an error message. |
| 29763 | Fix | Polish help was unreadable. |
| 29790 | Fix | Compensate for margins did not always work as intended on Canon |
| | | printers. |

Changes in version 4.2.1

| 28983 | Fix | Using auto size on iFLEX above 600dpi resulted in wrong size. |
|-------|-----|---|
| 29335 | Fix | Printing a multipage document resulted in first page being printed multiple |
| | | times and none of the other pages being printed. |
| 29335 | Fix | Improved stitching of oversize scans (scans larger than A2/C-size) on |
| | | flatbed scanner. |
| 29398 | Fix | Scanner name was not updated when activating the scanner (license) |
| 29622 | | while the program was running. |
| 29438 | Fix | Saving an opened 1bit file resulted in an 8bit file and sometimes an error |
| 29531 | | message. |
| | Fix | Several user interface corrections. |

Changes in version 4.2

| | New | Support for 'The New ScanStation', including new 'History' feature. |
|-------|-----|---|
| 28746 | New | List of Release Notes now accessible from Help menu. |
| 28895 | New | New button in 'On Screen Keyboard' (in Touch Screen mode) to switch |
| | | keyboard between selected language and English. The feature allows entering English names and destinations for all languages. |
| 28908 | New | New touch-friendly browse dialog in Touch Screen mode. |
| 28943 | New | New preset option in 'Save in' panel for often used folder and network |
| | | destinations. |
| 29110 | New | Support for HP Designjet T3500 and Z5400. |
| 29157 | New | Improved deskew detection when using 'Auto Alignment'. |
| 29494 | New | Improved speed of LZW compression. |
| 28661 | Fix | When entering 'File name', the template field <mypictures> was</mypictures> |
| | | allowed. |
| 28770 | Fix | 'ISO B' was sometimes default in 'First Time Setup' dialog. |
| | İ | |

| 28802 | Fix | 'Image Changed' dialog was sometimes shown behind the main window. |
|-------|-----|--|
| 28891 | Fix | When copying B&W or grayscale to HP Desingjet Z3200 an error |
| | | occurred. |
| 28954 | Fix | Opening file with .jpeg extension caused Nextimage to crash. |
| 29092 | Fix | Using Sharpen (in Image Adjustments) sometimes caused Nextimage to |
| | | become unresponsive. |
| 29098 | Fix | Making a CLC profile for Canon iPF820 resulted in an error. |
| 29100 | Fix | When making a CLC profile sometimes an error occurred. |
| 29102 | Fix | Sometimes Nextimage did not start correctly, showing a red cross in lower |
| | | right corner. |
| 29109 | Fix | Cancel reacted very slowly. |
| 29333 | Fix | When paper jam occurred during Copy then print job was still sent to |
| | | printer. |
| 29337 | Fix | When using ATAC (scanning thick originals) with 'Auto Size' no scanning |
| | | was performed. |
| 29352 | Fix | It was possible to generate invalid TIF files above 4GB. |
| 29377 | Fix | Resize (in Image Adjustments) to fixed size was not working when using |
| | | auto input size. |
| 29423 | Fix | Using Manual Align (in Image Adjustments) and fixed input size resulted in |
| | | a corrupt file. |
| _ | Fix | Several user interface corrections. |

Changes in version 4.1.2

| 28769 | New | Improved A1/D-size scans on iFLEX flatbed scanners. |
|-------|-----|---|
| 28829 | New | Improved 'Auto Size' on iFLEX flatbed scanners. |
| 28881 | New | Improved 'Auto Alignment'. |
| 27454 | Fix | Aligning the image could cause jaggy lines. |
| 27597 | Fix | 1-261 error could occur followed by the program being unresponsive. |
| 28722 | Fix | Splash screen was sometimes displayed too long when using TWAIN. |

Changes in version 4.1.1

| 28069 | New | Support for Canon iPF680/685/780/785, iPF |
|-------|-----|---|
| 28458 | | 6400SE/6410SE/8400SE/8410SE |
| 28566 | New | Allow image adjustments when using Indexed Color. |
| 28507 | New | Support for HP DesignjetT795/T795ps, Designjet |
| 28567 | | Z6600/Z6600ps/Z6800/Z6800ps |
| 27721 | New | Startup in TWAIN mode after Windows reboot if Nextimage was last used in |
| | | TWAIN mode. |
| 28461 | New | Support for Océ Plotwave 750 |
| 28568 | New | Support for Epson SC-T3200/T5200/T5200D/T7200/T7200D |
| 27575 | Fix | Using 'Reset all Settings' caused paper frame to disappear from current |
| | | scan. |
| 27620 | Fix | Using 'Auto Length', but not 'Auto Width', on iFlex scanner resulted in wrong |
| | | scan area. |
| 28236 | Fix | Sometimes unable to use scanner after Nextimage restored from |
| | | Notification Area. |
| 28332 | Fix | Cancelling 'No Media' dialog caused Nextimage to become unresponsive. |
| 28500 | Fix | Scans with rotation sometimes resulted in error. |
| 28518 | Fix | Making Indexed Color preview in TWAIN caused Nextimage to become |

| | | unresponsive. |
|-------|-----|--|
| 28598 | Fix | Making Indexed Color Copy sometimes caused Nextimage to become unresponsive. |
| 28624 | Fix | Not possible to select printers using Windows drivers. Only printers using application |

Changes in version 4.1

| 27267 | New | Performance and memory usage improved. |
|-------|-----|---|
| 22490 | New | Supported Canon media for different medias merged into common list, to |
| | | avoid the need for specifying region in printer settings. |
| 25868 | New | Sharpen and Smoothen Image Adjustments added to B&W Threshold |
| | | Image Type. |
| 26496 | New | Search for scanner during application start-up now continues until one is |
| | | found or user cancel search. |
| 27315 | New | Added 'From name' to 'Email Setup' |
| 27389 | New | Display of Help now integrated in application instead of using default web |
| | | browser. |
| 27417 | New | |
| | | Default compression for CALS file format changed to Type 1. |
| 27455 | New | Bi-directional communication to HP Designjet T920, T1500, T2500 for |
| | | reading installed media etc. |
| 27924 | New | Default of 'Auto size to' changed to 'Any size'. |
| 27392 | Fix | Some predefined presets did not include the state for 'Auto' option of B&W |
| | | Points. |
| 27466 | Fix | It was not possible to remove a created 'Output ICC profile'. |
| 27553 | Fix | Using 'Align to Measure Line' in the Rotate/Mirror panel with a vertical |
| | | measure line caused image to be rotated 90°. |
| 28160 | Fix | Printing to HP T610 did not work. |
| 28162 | Fix | Pressing the (green) Start button on the iFlex scanner while the |
| | | application was not running caused an error. |
| 28183 | Fix | Colors in auto palette could be bad dependent on setup in 24 bit Color. |
| 28221 | Fix | Starting application from Notification Area with a scanner in sleep caused |
| | | an error. |
| 28226 | Fix | Indexed color gave 24 bit file if using Manual Palette and 'Apply palette in |
| | | view' was not checked. |
| 28260 | Fix | Exceeding maximum length or width of 200 inches when writing PDF files |
| | | did not show a message. |
| 28277 | Fix | Selecting a very small area in the image viewer while using Sharpen could |
| | | cause a crash. |
| 28303 | Fix | If scanning to a multipage file after scanning to certain single page formats |
| | | resulted in the first scan being saved to a single page file. |
| 28354 | Fix | |
| | | It was not possible to use the application from multiple logged in users on |
| | | the same PC. |
| 28361 | Fix | Pressing Scan button quickly after changing a setting could cause an |
| | | error. |
| | | Several user interface corrections. |

| 27885 | New | Advanced dimensional corrections (Accuracy Lens Enhancement and Enhance Horizontal Accuracy) are now disabled by default. |
|-------|-----|---|
| | | · · · · · · · · · · · · · · · · · · · |
| 27752 | Fix | After use of auto size, subsequent scans would be missing the top edge of |
| | | the image. |
| 27762 | Fix | Scanning using B&W Adaptive in high resolution could cause an |
| | | application error. |
| 27811 | Fix | Waking scanner after sleep could cause an application error. |
| 27827 | | |
| 27862 | Fix | Scanning on a monochrome scanner caused an application error. |
| 27898 | Fix | Saving multipage files in the File task caused an application error. |

Changes in version 4.0.2

| 27314 | New | Allow preview when scanning to email or TWAIN. |
|-------|-----|---|
| 27386 | New | Support for HP Designjet Z5400. |
| 27533 | New | Warn users during install if new license key will be needed. |
| 27586 | New | Individual set of predefined presets for CIS and CCD scanners. |
| 27617 | Fix | Opening a multipage file could change file type for subsequent scans. |
| 27678 | Fix | Partial image remained in viewer if scan was cancelled. |
| 27672 | Fix | Using Autosize in the TWAIN driver could cause an application error. |
| 27707 | Fix | Starting TWAIN driver could fail. |
| 27737 | Fix | Sharpen, Smoothen and B&W Adaptive was not always applied correctly |
| | | to image during scan to file (introduced in 4.0.1). |

Changes in version 4.0.1

| 27400 | New | Support for Epson SC-T3050/5050/7050, SC-T3070/5070/7070, SC-T3080/5080/7080. |
|-------|-----|---|
| 27558 | New | 30 days trial period when installed on PCs with older versions. |
| 27488 | Fix | The Product Improvement Program dialog could be displayed before |
| | | Nextimage was visible. |
| 27494 | Fix | Auto size selection was not remembered after a Windows reboot. |
| 27505 | Fix | Compensate for printer margins did not always have the desired effect. |
| 27520 | Fix | Accounting statistics did not include oversize scans (scans larger than |
| | | A2/C-size) on flatbed scanner. |
| 27522 | Fix | Improved display quality of Sharpen, Smoothen and B&W Adaptive when |
| | | zoomed out in image view. |
| | Fix | Miscellaneous user interface corrections. |

Changes in version 4.0

| 26694 | New | Support for new Contex HD iFLEX scanners. |
|-------|-----|--|
| 26895 | New | SnapScan workflow for improved performance. |
| 26903 | New | Support for HP Designjet T2500. |
| 26956 | New | Scan up to A1/D-size document on an A2/C-size flatbed scanner. |
| 26959 | New | Improved startup speed by minimizing application to Windows Notification |
| | | Area. |
| 26960 | New | Integrated email functionality using SMTP. |
| | | Note that to send emails larger than 3 MB Microsoft .NET Hotfix |
| | | KB2183292 is required. |
| 27032 | New | Support for Canon iPF64x0S, iPF84x0S. |
| | | |

| 27149 | New | Redesigned application help, and translation added for Dutch, Italian and |
|-------|-----|---|
| | | Korean. |
| 27174 | New | Support for Mutoh RJ-900X, RJ-901X. |
| 27266 | New | Improved speed when saving to TIF files using LZW compression. |
| 27426 | New | Improved speed when saving to file. |
| 26079 | Fix | Missing warning when closing application with edited image in the File |
| | | Task. |
| 26689 | Fix | No media in Canon iPF820 caused an application error. |
| 26796 | Fix | Printing on a Canon iPF750 using USB could cause an application error. |
| 27119 | Fix | Descreening and Turbo resolution modes could generate files with wrong |
| | | resolution. |
| 27175 | Fix | Media list contained invalid medias for Océ ColorWave and PlotWave |
| | | printers. |
| 27215 | Fix | Mixing color and monochrome pages in PDF/A multipage files caused an |
| | | application error. |
| | | Several user interface corrections. |

Supported Operating Systems

- Windows Vista (Business) 32-bit
- Windows Vista (Business) 64-bit
- Windows 7 (Enterprise) 32-bit
- Windows 7 (Enterprise) 64-bit
- Windows Server 2008 (Standard Edition), 64-bit
- Windows 8.1 (Enterprise) 32-bit
- Windows 8.1 (Enterprise) 64-bit
- Windows 10 (Enterprise) 32-bit
- Windows 10 (Enterprise) 64-bit

Supported Scanners

- IQ 2420
- IQ 2490
- IQ 4420
- IQ 4450
- IQ 4490
- CG710
- CG810
- IQ Quattro 2420
- IQ Quattro 2450
- IQ Quattro 2490u
- IQ Quattro 2490
- IQ Quattro 4420
- IQ Quattro 4450
- IQ Quattro 4490u
- IQ Quattro 4490
- SD One
- SD3610

- SD3610+
- SD3615 MFP
- SD3619
- SD3620
- SD3650+
- SD3690+
- HD Ultra 3610
- HD Ultra 3610+
- HD Ultra 3610i
- HD Ultra 3610i+
- HD Ultra 3630
- HD Ultra 3630+
- HD Ultra 3630i
- HD Ultra 3630i+
- HD Ultra 4210
- HD Ultra 4210+
- HD Ultra 4210i
- HD Ultra 4210i+
- HD Ultra 4230
- HD Ultra 4230+
- HD Ultra 4230i
- HD Ultra 4230i+
- HD Ultra 3650+
- HD Ultra 3650i+
- HD Ultra 3690i+
- HD Ultra 4250+
- HD Ultra 4250i+
- HD Ultra 4290i+
- HD Ultra i3610s
- HD Ultra i3620s
- HD Ultra i3650s
- HD Ultra i3690s
- HD Ultra i4210s
- HD Ultra i4220s
- HD Ultra i4250s
- HD Ultra i4290s
- HD iFLEX
- HD iFLEXu
- HD5430
- HD5450

Supported Printers

The application supports the below range of printers. If you do not find the relevant printer in the list, many other printers are indirectly supported by creating your own Printer Profile, or by printing to a hot-folder.

- Canon BJ-W3000
- Canon BJ-W3050

- Canon BJ-W7000
- Canon iPF500
- Canon iPF510
- Canon iPF600
- Canon iPF605
- Canon iPF610
- Canon iPF650 (qualified with Plain Paper and Coated Paper only)
- Canon iPF655 (qualified with Plain Paper and Coated Paper only)
- Canon iPF670
- Canon iPF671
- Canon iPF680
- Canon iPF685
- Canon iPF700
- Canon iPF710
- Canon iPF720
- Canon iPF750 (qualified with Plain Paper and Coated Paper only)
- Canon iPF755 (qualified with Plain Paper and Coated Paper only)
- Canon iPF760
- Canon iPF765
- Canon iPF770
- Canon iPF771
- Canon iPF780
- Canon iPF785
- Canon iPF810 (qualified with Plain Paper and Coated Paper only)
- Canon iPF815 (qualified with Plain Paper and Coated Paper only)
- Canon iPF820 (qualified with Plain Paper and Coated Paper only)
- Canon iPF825 (qualified with Plain Paper and Coated Paper only)
- Canon iPF5000
- Canon iPF5100
- Canon iPF6000S
- Canon iPF6100
- Canon iPF6200
- Canon iPF6300
- Canon iPF6350
- Canon iPF6300S
- Canon iPF64x0S
- Canon iPF64x0SE
- Canon iPF8000
- Canon iPF8000S
- Canon iPF8100
- Canon iFP8300
- Canon iPF8300S
- Canon iPF8310
- Canon iPF8310S
- Canon iPF84x0S
- Canon iPF84x0SE
- Canon iPF9000

- Canon iPF9000S
- Canon iPF9100
- Canon W6200PG
- Canon W6400D
- Canon W6400PG
- Canon W7200
- Canon W8200
- Canon W8200PG
- Canon W8400
- Canon W8400D
- Canon W8400PG
- Encad NovaJet 500
- Encad NovaJet 630
- Encad NovaJet 700
- Encad NovaJet 750
- Encad NovaJet 850
- Encad NovaJet 1000i
- Encad NovaJet PRO 600e
- Encad NovaJet PRO
- Encad NovaJet PROe
- Epson Stylus Pro 4400
- Epson Stylus Pro 4800
- Epson Stylus Pro 7000
- Epson Stylus Pro 7400
- Epson Stylus Pro 7600
- Epson Stylus Pro 7700
- Epson Stylus Pro 7710
- Epson Stylus Pro 7800
- Epson Stylus Pro 7880
- Epson Stylus Pro 7880C
- Epson Stylus Pro 7890
- Epson Stylus Pro 7900
- Epson Stylus Pro 7910
- Epson Stylus Pro 9000
- Epson Stylus Pro 9400
- Epson Stylus Pro 9600
- Epson Stylus Pro 9700
- Epson Stylus Pro 9710
- Epson Stylus Pro 9800
- Epson Stylus Pro 9880
- Epson Stylus Pro 9880C
- Epson Stylus Pro 9890
- Epson Stylus Pro 9900
- Epson Stylus Pro 9910
- Epson Stylus Pro 10000
- Epson Stylus Pro 10600
- Epson Stylus Pro 11880

- Epson Stylus Pro 11880C
- Epson SureColor SC-P6000
- Epson SureColor SC-P7000
- Epson SureColor SC-P8000
- Epson SureColor SC-P9000
- Epson SureColor SC-T3000
- Epson SureColor SC-T3200
- Epson SureColor SC-T5000
- Epson SureColor SC-T5200
- Epson SureColor SC-T5200D
- Epson SureColor SC-T7000
- Epson SureColor SC-T7200
- Epson SureColor SC-T7200D
- Gestetner GWD2004
- Gestetner GWD2006
- Gestetner SP W2470
- HP DesignJet 70
- HP DesignJet 90
- HP DesignJet 110
- HP DesignJet 111
- HP DesignJet 120
- HP DesignJet 130
- HP DesignJet 500 (HP-GL/2)
- HP DesignJet 500PS (HP-GL/2)
- HP DesignJet 510 (HP-GL/2)
- HP DesignJet 510PS (HP-GL/2)
- HP DesignJet 750C
- HP DesignJet 800
- HP DesignJet 800PS
- HP DesignJet 1050C
- HP DesignJet 1055CM
- HP DesignJet 2000CP
- HP DesignJet 2500CP
- HP DesignJet 3000CP
- HP DesignJet 3500CP
- HP DesignJet 4000
- HP DesignJet 4000ps
- HP DesignJet 4020
- HP DesignJet 4020ps
- HP DesignJet 4500
- HP DesignJet 4500mfp
- HP DesignJet 4500ps
- HP DesignJet 4520
- HP DesignJet 4520mfp
- HP DesignJet 4520ps
- HP DesignJet 5000
- HP DesignJet 5000PS

- HP DesignJet 5500
- HP DesignJet 5500PS
- HP DesignJet T610
- HP DesignJet T610ps
- HP DesignJet T620
- HP DesignJet T620ps
- HP DesignJet T730
- HP DesignJet T770
- HP DesignJet T770ps
- HP DesignJet T770 24
- HP DesignJet T770ps 24
- HP DesignJet T790
- HP DesignJet T790ps
- HP DesignJet T795
- HP DesignJet T795ps
- HP DesignJet T830 MFP
- HP DesignJet T920
- HP DesignJet T920ps
- HP DesignJet T930
- HP DesignJet T930ps
- HP DesignJet T1100
- HP DesignJet T1100ps
- HP DesignJet T1120
- HP DesignJet T1120mfp
- HP DesignJet T1120ps
- HP DesignJet T1200
- HP DesignJet T1200ps
- HP DesignJet T1300
- HP DesignJet T1300ps
- HP DesignJet T1500
- HP DesignJet T1500ps
- HP DesignJet T1530
- HP DesignJet T1530ps
- HP DesignJet T2300
- HP DesignJet T2300ps
- HP DesignJet T2500
- HP DesignJet T2500ps
- HP DesignJet T2530
- HP DesignJet T2530ps
- HP DesignJet Z2100
- HP DesignJet Z2110
- HP DesignJet Z3100
- HP DesignJet Z3100ps
- HP DesignJet Z3200
- HP DesignJet Z3200ps
- HP DesignJet Z5200
- HP DesignJet Z5200ps

- HP DesignJet Z5400
- HP DesignJet Z5400ps
- HP DesignJet Z6100
- HP DesignJet Z6100ps
- HP DesignJet Z6200
- HP DesignJet Z6200ps
- HP DesignJet Z6600
- HP DesignJet Z6600ps
- HP DesignJet Z6800
- HP DesignJet Z6800ps
- HP DesignJet T7100
- HP DesignJet T7100ps
- HP DesignJet T7200
- HP DesignJet T7200ps
- HP PageWide XL 4000
- HP PageWide XL 4000 MFP
- HP PageWide XL 4000PS
- HP PageWide XL 4000PS MFP
- HP PageWide XL 4500
- HP PageWide XL 4500 MFP
- HP PageWide XL 4500PS
- HP PageWide XL 4500PS MFP
- HP PageWide XL 5000
- HP PageWide XL 5000 Blueprinter
- HP PageWide XL 5000 MFP
- HP PageWide XL 5000PS
- HP PageWide XL 5000PS Blueprinter
- HP PageWide XL 5000PS MFP
- HP PageWide XL 8000 Blueprinter
- HP PageWide XL 8000PS
- HP PageWide XL 8000PS Blueprinter
- Imagio MP W3600
- Imagio MP W2400
- Lanier LP124w
- Lanier LW324
- Lanier LW326
- Mutoh RJ-900C
- Mutoh RJ-901C
- Mutoh RJ-900X
- Mutoh RJ-901X
- Mutoh RJ-4000
- Mutoh RJ-4100
- Mutoh RJ-8000
- NRG MP W2400
- NRG MP W3600
- NRG SP W2470
- Océ 535X-42

- Océ 535X-60
- Océ 535X-600-42
- Océ 535X-600-60
- Océ ColorWave 300
- Océ ColorWave 500
- Océ ColorWave 550
- Océ ColorWave 600
- Océ ColorWave 650
- Océ ColorWave 700
- Océ ColorWave 810
- Océ ColorWave 900
- Océ ColorWave 910
- Océ CS5050
- Océ CS5070
- Océ PlotWave 300
- Océ PlotWave 340
- Océ PlotWave 350
- Océ PlotWave 360
- Océ PlotWave 500
- Océ PlotWave 750
- Océ PlotWave 900
- Océ TCS300
- Océ TCS400
- Océ TCS500
- Océ TDS300
- Océ TDS320
- Océ TDS400
- Océ TDS450
- Océ TDS600
- Océ TDS700
- Océ TDS750
- Océ TDS800
- Océ TDS860
- Ricoh Aficio MP W2400
- Ricoh Aficio MP W3600
- Ricoh Aficio SP W2470
- Roland Hi-Fi JET FJ-40
- Roland Hi-Fi JET FJ-50
- Roland Hi-Fi JET FJ-540
- Roland Hi-Fi JET FJ-740
- Savin 2404WD
- Savin 2404WDP
- Savin 2406WD
- Seiko LP-1010
- Selex SG-950T
- Xerox 6204
- Xerox 8825

Xerox 8830