

SERVICE BULLETIN

SB001

NON-MANDATORY UPDATE

DATE: March, 3rd 2021

MODELS AFFECTED: 83HD+

ALLOWABLE HOURS: 6 hours

SUBJECT: Upper Boom Inspection and Update

The content of this Service Bulletin is intended for Owners/Dealers/Distributors of the CMC S25/83HD+ lift.

For media-related uses, please contact marketing@cmclift.com

ISSUE

On this specific model, any use that does not comply with the technical requirements, regulations, and limitations of the lift set forth in the CMC 83HD+ Owner's Manual or is against the warnings placed on the lift may result in damage to the upper boom.

! WARNING

Application of a force or load on the boom which is greater than the amounts set forth in the Owner's Manual, on the Warning stickers, and on the ID plate attached to the machine, could compromise the integrity of the upper boom.



SERVICE BULLETIN

SB001

ACTION

The owner must inspect their equipment and check for any possible damage on the bottom part of it as per Picture 1 and Picture 2.

In case the boom has no evident damage on the bottom part, the boom can be considered safe and can be used according with technical requirements and regulations.

Owners can contact their Dealer or CMC to perform a structural update on the above mentioned boom, free of charge for the owners if the update is performed at a CMC authorized Service Point or at Dealer location.

⚠ WARNING

If the owner's inspection reveals any damage to the boom section in the spot specified in the sample picture in the Figure 1, the owner **MUST** stop any use of the lift immediately and contact a Dealer or CMC directly.

As a reminder, the machine's Owner's Manual requires daily inspection of the machine and to perform periodically the maintenance, according with the working hours and the general conditions of the machine.

As an additional reminder to owners and users, as dictated by OSHA regulations, before operating a mobile elevating work platform (MEWP), the operator must be trained and familiarized with the machine. Owners and users must have proof of specific training and familiarization performed by a qualified person.

NOTE TO OWNERS

If the Manufacturer or its Dealer has failed or is unable to perform the update without charge or within a reasonable amount of time you can notify:

Administrator
Via Bitritto, 119 - 70124 Bari - Italy
+39.080.53.26.606
management@cmclift.com

www.cmclift.com/en/assistenza/servicebulletin

If you require additional copies of this bulletin or have any question, please contact CMC Utilities at +390805326606 or at service4@cmclift.com