

Contex LINK change Log

Contents

[Version Changes](#)

[Supported Scanners](#)

Version Changes

Changes in version 3.79450

| | | |
|-------|-----|--|
| 34698 | New | Verified Publisher displayed in Windows security warning |
| 34651 | New | Hint texts in Setup are now translated |

Changes in version 2.77698

| | | |
|-------|-----|--|
| 77439 | New | Support for new scanner |
| 33780 | Fix | Remove button did not work properly |
| 34177 | Fix | Fields in the main window list was by mistake editable |
| 77432 | Fix | Close button in system menu did not work |

Changes in version 1.70029

| | | |
|--|-----|-----------------|
| | New | Initial release |
| | New | |

Supported Scanners

The Contex LINK software supports the following scanners.

- SD One MF
- IQ FLEX