

SD One MF software change Log

Contents

[Version Changes](#)
[Supported Printers](#)

Version Changes

Changes in version 4.0.1-030

SDMF-27	New	Support for new 2nd source component added
---------	-----	--

Changes in version 4.0.1-029

	New	Embedded OS updated with latest security patches
	Fix	Sometimes auto size detection did not work

Changes in version 4.0.1-028

	New	Support for new Nextimage 7 license system
--	-----	--

Changes in version 4.0.1-027

	New	Embedded OS updated with latest security patches
	Security	The web interface (Administrator Console) changed to use the HTTPS protocol instead of plain HTTP Requires installation of certificate in the web browser used.
	New	Support for new printers added (Canon, Epson, HP) HP DesignJet T850, T950, XT950, T850 MFP, T950 MFP, XT950 MFP Canon PRO-520S, PRO-4600, PRO-546, PRO-566, PRO-6600 Canon TX-2200, TX-3200, TX-4200, TX-5220, TX-5320, TX-5420 Canon TZ-32000, TZ-5320 Canon GP-4600S, GP-546S, GP-566S, GP-6600S EPSON SC-P6500, SC-P6500D, SC-P7500, SC-P7530, SC-P7540, SC-P7550, SC-P7560, SC-P7570, SC-P7580 SC-P8500D, SC-P8500DL, SC-P9500, SC-P9530, SC-P9540, SC-P9550, SC-P9560, SC-P9570, SC-P9580

Changes in version 4.0.1-024

	New	Support for Multi Exposure scanning (requires WIDEsystem 6 & Nextimage 6)
	New	ICC Profile naming changed to comply with FADGI implementation

Changes in version 4.0.1-023

	New	Embedded OS updated with latest security patches
IQF-13	New	Support for Canon: GP-200, GP-2000, GP-300, GP-4000, GP-520, GP-5200, GP-5300, GP-540, TM-240, TM-250, TM-255, TM-340, TM-350, TM-355, TM-5240, TM-5250, TM-5255, TM-5340, TM-5350, TM-5355
	New	Support for HP: HP DesignJet T630 24-in, HP DesignJet T630 36-in
	New	Support for EPSON: SC-T3700, SC-T3700D, SC-T5700D, SC-T7700D, SC-T7700DL, SC-T3730, SC-T3730D, SC-T5730D, SC-T7730D, SC-T7730DL, SC-T3740, SC-T3740D, SC-T5740D, SC-T7740D, SC-T7740DL, SC-T3750, SC-T3750D, SC-T5750D, SC-T7750D, SC-T7750DL, SC-T3760, SC-T3760D, SC-T5760D, SC-T7760D, SC-T7760DL, SC-T3770, SC-T3770D, SC-T5770D, SC-T7770D, SC-T7770DL, SC-T3780, SC-T3780D, SC-T5780D, SC-T7780D, SC-T7780DL, SC-T3790, SC-T3790D, SC-T5790D, SC-T7790D, SC-T7790DL

Changes in version 4.0.1-022

SDMF-2	Fix	Sometimes the saved TIF files were invalid
SDMF-3	Fix	Scan to LAN didn't work with spaces in the folder name

Changes in version 4.0.1-021

P4-95869	New	Embedded OS updated with latest security patches
38529	Fix	Sometimes an update was started without a new version being available
P4-95560	Fix	Invalid FW and OS files weren't validated before update through USB was started

Changes in version 4.0.1-019

38426	New	New scan destination: Network Drive
38427 38463	New	Support for Canon: TX-2100, 3100, 4100, 5210, 5310, 5410 TZ-30000, 5300 Support for HP: DesignJet T940, DesignJet Z6 Pro, DesignJet Z9 Pro

PageWide XL 3920, PageWide XL 4200,
PageWide XL 4700, PageWide XL 5200,
PageWide XL 8200

38420	New	Increased security by allowing alphanumeric characters in system password
-------	-----	---

Changes in version 4.0.1-018

37984	New	Printer status screen has been re-designed.
38233	New	New scan destination: Secure FTP server.
38225	New	Icons in scroll menu can be controlled by the user.
38226	New	Update scanner with latest security patches.
38000	Fix	Scanner sleep timer is no longer being reset to 15 minutes after a calibration.
38044	Fix	The 150 dpi scan speed was too low on some scanners.
38022	Fix	Faster calibration.
37985	Fix	Auto cut on EPSON SC-T34XX and T54XX.

Changes in version 4.0.1-017

37769	Fix	Some scanners could not be awakened from sleep mode
-------	-----	---

Changes in version 4.0.1-016

37328	New	Contex Link v.7 stored in scanner.
37458	New	Actual levels are displayed when image is validated.
37400	New	Rainforest support is withdrawn.
37335	Fix	Support for HP DesignJet Z9 with single roll.
37446	Fix	Spanish and Russian User Guides are now available from scanner web page.

Changes in version 4.0.1-015

37186	New	Support for EPSON: SC-T3400, SC-T3450, SC-T3470, SC-T3480 SC-T5400, SC-T5450, SC-T5470, SC-T5480
37176 37171	New	Support for Energy Star 3.0 for scanners produced after September 2019
37180	Fix	Sometimes error message "FPGA PCI INTERFACE NOT READY" was displayed due to invalid flash writing procedure.

Changes in version 4.0.1-014

-	New	Common SD One MF and IQ FLEX code
36975	New	Support for EPSON: SC-T3050/SC-T3070/SC-T3080 SC-T5050/SC-T5070/SC-T5080 SC-T7050/SC-T7070/SC-T7080 SC-T3200D/SC-T5200D Canon: iPF710, PRO-6000 HP: DesignJet T1600, DesignJet T2600, DesignJet XL 3600
36252	New	Support for HP T1708 and T1708dr
36528	New	Canon TM-300 Can't load CLC
37041	Fix	Canon iPF 6400 printer prints only half CLC sheets
33236	Fix	No icon in Rainforest when no Ethernet connection
33593	Fix	Scanner scanned 48.97" when 50" was specified

Changes in version 4.0.1-013

36524	New	Support for HP DesignJet T1708 and T1708dr series.
36385	New	Support for Canon TM-200, TM-205, TM-300, TM-305, TM-5200, TM-5205, TM-5300 and TM-5305
36528	New	Contex Link v.5 stored in scanner.

Changes in version 4.0.1-012

35868	New	Support for HP DesignJet Z6610 and Z6810 Printer series.
35867	New	Support for HP DesignJet Z6 and Z9 Printer series.
35710	Fix	Connection problem with HP DesignJet T7X00ps

Changes in version 4.0.1-011

34747	New	Support for HP DesignJet T1700 Printer series.
35305	Fix	Media profile requirement for Blueprint paper removed.
35342	Fix	No message when JPEG file format limit was reached.
35224	Fix	B&W copy with low scan quality failed.
35362	Fix	B&W copies on the Canon Pro 4000s printer failed.

Changes in version 4.0.1-010

35165	New	Contex Link v.4 stored in scanner.
34996	New	Support for Canon imagePROGRAF TX Series.
34706	New	Sleep button in upper left corner of Main window.
34995	New	Touch panel access can be locked from scanner web interface.
34892	New	Password protection of Software update.
34701	Fix	Mail subject was sometimes not displayed correct in recipient's mail system.
35098	Fix	Custom media types is now supported on HP printers.

Changes in version 4.0.1-009

Change	New strings in Scan /Copy Quality menu.	
	Translation Updated	

Fix	Media enquiry on T930, T1530 and T2530 were fixed
Fix	Some Canon printers (SE models?) did not work
Fix	Changed load of touch driver (new OS)

Changes in version 4.0.1-008

Fix	Location of rainforest365 icon was incorrect.
Fix	Scanner sometimes froze after sleep
Fix	Contex Link updated to latest version
Fix	Improved bidirectional support for the Canon PRO printer models
Fix	Dual roll support on Epson SC-TxxxD models didn't work
Fix	Improved USB key support
	Misc. updates to user interface.

Supported Printers

The SD One MF supports the below range of printers.

- Canon GP-200
- Canon GP-2000
- Canon GP-300
- Canon GP-4000
- Canon GP-4600S
- Canon GP-520
- Canon GP-5200
- Canon GP-5300
- Canon GP-540
- Canon GP-546S
- Canon GP-566S
- Canon GP-6600S
- Canon iPF5000
- Canon iPF510
- Canon iPF5100
- Canon iPF610
- Canon iPF6300
- Canon iPF6300S
- Canon iPF6350
- Canon iPF6400
- Canon iPF6400S
- Canon iPF6400SE
- Canon iPF6410S
- Canon iPF6410SE
- Canon iPF6450
- Canon iPF670
- Canon iPF671
- Canon iPF680
- Canon iPF681
- Canon iPF685
- Canon iPF686
- Canon iPF710
- Canon iPF760
- Canon iPF765
- Canon iPF770
- Canon iPF771
- Canon iPF780
- Canon iPF781
- Canon iPF785
- Canon iPF786
- Canon iPF8000
- Canon iPF8000S
- Canon iPF8100
- Canon iPF815
- Canon iPF820
- Canon iPF825
- Canon iPF830
- Canon iPF8300
- Canon iPF8300S
- Canon iPF831
- Canon iPF8310
- Canon iPF8310S
- Canon iPF840
- Canon iPF8400
- Canon iPF8400S
- Canon iPF8400SE
- Canon iPF841

- Canon iPF8410S
- Canon iPF8410SE
- Canon iPF850
- Canon iPF851
- Canon iPF9000
- Canon iPF9000S
- Canon iPF9100
- Canon iPF9400
- Canon iPF9400S
- Canon PRO-1000
- Canon PRO-2000
- Canon PRO-2100
- Canon PRO-4000
- Canon PRO-4000S
- Canon PRO-4100
- Canon PRO-4100S
- Canon PRO-4600
- Canon PRO-500
- Canon PRO-520
- Canon PRO-520S
- Canon PRO-521
- Canon PRO-540
- Canon PRO-540S
- Canon PRO-541
- Canon PRO-541S
- Canon PRO-546
- Canon PRO-560
- Canon PRO-560S
- Canon PRO-561
- Canon PRO-561S
- Canon PRO-566
- Canon PRO-6000
- Canon PRO-6000S
- Canon PRO-6100
- Canon PRO-6100S
- Canon PRO-6600
- Canon TA-20
- Canon TA-30
- Canon TA-5200
- Canon TA-5300
- Canon TM-200
- Canon TM-205
- Canon TM-240
- Canon TM-250
- Canon TM-255
- Canon TM-300
- Canon TM-305
- Canon TM-340
- Canon TM-350
- Canon TM-355
- Canon TM-5200
- Canon TM-5205
- Canon TM-5240
- Canon TM-5250
- Canon TM-5255
- Canon TM-5300
- Canon TM-5305
- Canon TM-5340
- Canon TM-5350
- Canon TM-5355
- Canon TX-2000
- Canon TX-2100
- Canon TX-2200
- Canon TX-3000
- Canon TX-3100
- Canon TX-3200
- Canon TX-4000
- Canon TX-4100
- Canon TX-4200
- Canon TX-5200
- Canon TX-5210
- Canon TX-5220
- Canon TX-5300
- Canon TX-5310
- Canon TX-5320

- Canon TX-5400
- Canon TX-5410
- Canon TX-5420
- Canon TZ-30000
- Canon TZ-32000
- Canon TZ-5300
- Canon TZ-5320
- EPSON SC-P6500
- EPSON SC-P6500D
- EPSON SC-P7500
- EPSON SC-P7530
- EPSON SC-P7540
- EPSON SC-P7550
- EPSON SC-P7560
- EPSON SC-P7570
- EPSON SC-P7580
- EPSON SC-P8500D
- EPSON SC-P8500DL
- EPSON SC-P9500
- EPSON SC-P9530
- EPSON SC-P9540
- EPSON SC-P9550
- EPSON SC-P9560
- EPSON SC-P9570
- EPSON SC-P9580
- EPSON SC-T3000
- EPSON SC-T3050
- EPSON SC-T3070
- EPSON SC-T3080
- EPSON SC-T3200
- EPSON SC-T3200D
- EPSON SC-T3250
- EPSON SC-T3250D
- EPSON SC-T3270
- EPSON SC-T3270D
- EPSON SC-T3400
- EPSON SC-T3405
- EPSON SC-T3450
- EPSON SC-T3455
- EPSON SC-T3470
- EPSON SC-T3475
- EPSON SC-T3480
- EPSON SC-T3485
- EPSON SC-T3700
- EPSON SC-T3700D
- EPSON SC-T3730
- EPSON SC-T3730D
- EPSON SC-T3740
- EPSON SC-T3740D
- EPSON SC-T3750
- EPSON SC-T3750D
- EPSON SC-T3760
- EPSON SC-T3760D
- EPSON SC-T3770
- EPSON SC-T3770D
- EPSON SC-T3780
- EPSON SC-T3780D
- EPSON SC-T3790
- EPSON SC-T3790D
- EPSON SC-T5000
- EPSON SC-T5050
- EPSON SC-T5070
- EPSON SC-T5080
- EPSON SC-T5100
- EPSON SC-T5150
- EPSON SC-T5170
- EPSON SC-T5180
- EPSON SC-T5200
- EPSON SC-T5200D
- EPSON SC-T5250
- EPSON SC-T5250D
- EPSON SC-T5270
- EPSON SC-T5270D
- EPSON SC-T5400
- EPSON SC-T5405

- EPSON SC-T5450
- EPSON SC-T5455
- EPSON SC-T5470
- EPSON SC-T5475
- EPSON SC-T5480
- EPSON SC-T5485
- EPSON SC-T5700D
- EPSON SC-T5730D
- EPSON SC-T5740D
- EPSON SC-T5750D
- EPSON SC-T5760D
- EPSON SC-T5770D
- EPSON SC-T5780D
- EPSON SC-T5790D
- EPSON SC-T7000
- EPSON SC-T7050
- EPSON SC-T7070
- EPSON SC-T7080
- EPSON SC-T7200
- EPSON SC-T7250
- EPSON SC-T7250D
- EPSON SC-T7270
- EPSON SC-T7270D
- EPSON SC-T7700D
- EPSON SC-T7700DL
- EPSON SC-T7730D
- EPSON SC-T7730DL
- EPSON SC-T7740D
- EPSON SC-T7740DL
- EPSON SC-T7750D
- EPSON SC-T7750DL
- EPSON SC-T7760D
- EPSON SC-T7760DL
- EPSON SC-T7770D
- EPSON SC-T7770DL
- EPSON SC-T7780D
- EPSON SC-T7780DL
- EPSON SC-T7790D
- EPSON SC-T7790DL
- HP DesignJet D5800
- HP Designjet T1100 24
- HP Designjet T1100 44
- HP Designjet T1120 24
- HP Designjet T1120 44
- HP Designjet T120
- HP Designjet T1200
- HP Designjet T1300
- HP Designjet T1500
- HP DesignJet T1530
- HP DesignJet T1530ps
- HP DesignJet T1600
- HP DesignJet T1600dr
- HP DesignJet T1700
- HP DesignJet T1700dr
- HP DesignJet T1708
- HP DesignJet T1708dr
- HP Designjet T2300
- HP Designjet T2500
- HP DesignJet T2530
- HP DesignJet T2530ps
- HP DesignJet T2600
- HP DesignJet T2600dr
- HP Designjet T3500
- HP Designjet T520 24in
- HP Designjet T520 36in
- HP Designjet T530 24-in Printer
- HP Designjet T530 36-in Printer
- HP Designjet T610 24
- HP Designjet T610 44
- HP Designjet T620
- HP Designjet T630 24-in
- HP Designjet T630 36-in
- HP Designjet T7100
- HP Designjet T7100 Monochrome
- HP Designjet T7200

- HP Designjet T730
- HP Designjet T770
- HP Designjet T770 24in
- HP Designjet T790 24in
- HP Designjet T790 44in
- HP Designjet T795 44in
- HP Designjet T830 MFP
- HP DesignJet T850
- HP DesignJet T850 MFP
- HP Designjet T920
- HP DesignJet T930
- HP DesignJet T930ps
- HP DesignJet T940
- HP DesignJet T950
- HP DesignJet T950 MFP
- HP DesignJet XL 3600
- HP DesignJet XT950
- HP DesignJet XT950 MFP
- HP Designjet Z2100 24
- HP Designjet Z2100 24 HPGL2
- HP Designjet Z2100 44
- HP Designjet Z2100 44 HPGL2
- HP DesignJet Z2600 24in PS HPGL2
- HP DesignJet Z2600 24in PS PCL3GUI
- HP DesignJet Z2600 24in PS PS3
- HP Designjet Z2600 PostScript
- HP DesignJet Z2600 PostScript Printer
- HP DesignJet Z2600 PS HPGL2
- HP DesignJet Z2600 PS PCL3GUI
- HP DesignJet Z2600 PS PS3
- HP Designjet Z3100 24
- HP Designjet Z3100 24 HPGL2
- HP Designjet Z3100 44
- HP Designjet Z3100 44 HPGL2
- HP Designjet Z3200 24
- HP Designjet Z3200 24 HPGL2
- HP Designjet Z3200 44
- HP Designjet Z3200 44 HPGL2
- HP Designjet Z5200
- HP Designjet Z5400 PostScript
- HP DesignJet Z5600 44in PS HPGL2
- HP DesignJet Z5600 44in PS PCL3GUI
- HP DesignJet Z5600 44in PS PS3
- HP DesignJet Z5600 PostScript
- HP DesignJet Z5600 PostScript Printer
- HP DesignJet Z5600 PS HPGL2
- HP DesignJet Z5600 PS PCL3GUI
- HP DesignJet Z5600 PS PS3
- HP DesignJet Z6 24in
- HP DesignJet Z6 44in
- HP DesignJet Z6 Pro
- HP Designjet Z6100 42
- HP Designjet Z6100 60
- HP Designjet Z6200 42
- HP Designjet Z6200 60
- HP Designjet Z6600 Production Printer
- HP Designjet Z6610 60in
- HP Designjet Z6800 Photo Production Printer
- HP Designjet Z6810 42in
- HP Designjet Z6810 60in
- HP DesignJet Z6dr 44in
- HP DesignJet Z9 24in
- HP DesignJet Z9 44in
- HP DesignJet Z9 Pro
- HP DesignJet Z9dr 44in
- HP DesignJet T850 MFP
- HP DesignJet XT950 MFP
- HP PageWide XL 3920 MFP
- HP PageWide XL 3920 PS MFP
- HP PageWide XL 4200 MFP series
- HP PageWide XL 4200 PS MFP series
- HP PageWide XL 4200 PS series
- HP PageWide XL 4200 series
- HP PageWide XL 4700 MFP series
- HP PageWide XL 4700 MFP series

- HP PageWide XL 4700 PS MFP series
- HP PageWide XL 4700 series
- HP PageWide XL 5200 MFP series
- HP PageWide XL 5200 PS MFP series
- HP PageWide XL 5200 PS series
- HP PageWide XL 5200 series
- HP PageWide XL 8200 PS series
- HP PageWide XL 8200 series