Wide Format Scanner System Software

Installation
SCANdump
Version Changes

Installation

This software can be run on Windows 2000, Windows XP and Windows 2003 Server (Standard Edition) and Windows Vista 32 bit platforms.

Drivers are compliant with the Windows STI (Still Image Architecture) / WIA (Windows Image Architecture) and support the Windows WIA Scanning Wizard.

SCANdump

A utility called SCANdump is installed together with this software. When running this utility all vital information stored in the scanner's non-volatile memory is saved to a file in your TEMP directory. In case of trouble with your scanner this file can be e-mailed to technical support in order to ease diagnostics of the problem.

Version Changes

ID	Note	
150	New	The scan2net SCANclient listens to more servers simultaneously.
	feature	
324	Bugfix	Some one-touch applications were not displayed under special circumstances.
340	Bugfix	Scan-to functionality used wrong dpi for very high dpi's.
355	New	Ok/Cancel/Apply buttons now works consistently on all tabs.
	feature	
359	Bugfix	Forgot to update the adjustment status field if the scanner were not been adjusted.
369	Bugfix	Fixed autosize problem when certain scanner were connected via. USB
370	Bugfix	Wrong color saturation method was used on 24bit scans
371	Bugfix	Some error messages for scanner were not shown correctly for the latest scanner models.
372	New	Safer FW download handling to avoid system deadlock caused by Windows device
	feature	locking mechanism.
373	Bugfix	Minor error in the color balance solved.
374	Change	Showing the application errorlog when pressing view log on log tab, instead of the
		scanner error log (which can still be found in the Windows folder if present).
378	Bugfix	Right click menu and About box now shows correct info for restricted users.
381	Bugfix	Timer setting and auto-standby revised.
383	Bugfix	Scan server not connecting correctly to clients
384	Bugfix	List of servers now updated correctly
388	Bugfix	Handling restricted user limitations on scan2net tab.
390	Bugfix	Better Autosize algorithm.
392	New	Using term Scan to Net because Scan2net have been registered as a protected term.
	feature	
397	Change	Some more error handling added.
399	Bugfix	Using term Power Down to use the correct Eergy Star terminology on the interface.

401	Bugfix	A problem sharing some special scanner models was solved.
402	Bugfix	SCANserver did not clean up unsent files and inactive users.
403	New	Energy star compliance assured
	feature	

Changes in version 3.4.2

ID	Note	
369	Bugfix	Fixed autosize problem on some scanners when connected via USB.
374	Change	Showing the application errorlog when pressing view log on log tab, instead of the
		scanner error log (scanner error log can be found in the Windows folder).
378	Bugfix	Right click menu and About box now shows correct info for restricted users.
381	Bugfix	Timer setting and auto-standby revised.
383	Bugfix	Scan server was not connecting correctly to clients.
384	Bugfix	List of servers is now updated correctly.
388	Bugfix	Handling restricted user limitations correctly on scan2net tab.
390	Bugfix	Improved Autosize algorithm.
392	Change	Using term Scan to Net instead of Scan2net.
397	Bugfix	Improved error logging.
399	Change	Using term Power Down to comply with Energy Star terminology.
401	Bugfix	A problem sharing some scanner models has been solved.
402	Bugfix	SCANserver did not clean up un-sent files and inactive users.
403	Change	Energy Star compliance assured.

Changes in version 3.4.1

ID	Note	
150	New	The scan2net SCANclient listens to more servers simultaneously.
	feature	
324	Bugfix	Some one-touch application were not displayed under special circumstances.
340	Bugfix	Scan-to functionality used wrong dpi for very high dpi's.
355	New	Ok/Cancel/Apply buttons now works consistently on all tabs.
	feature	
359	Bugfix	Forgot to update the adjustment status field if the scanner were not been adjusted.
370	Bugfix	Wrong color saturation method was used on 24bit scans
371	Bugfix	Some error messages for scanner were not shown corretly for the latest scanner models.
372	New	Safer FW download handling to avoid system deadlock caused by Windows device
	feature	locking mechanism.
373	Bugfix	Minor error in the color balance solved.

ID	Note	
313	New	We now handle PC standby/hibernate situations.
	feature	
322	Bugfix	Selecting link days on timer tab no longer applies to all scanners connected. Only the
		selected one.
336	Bugfix	In the scan2net client the user could not delete a password once selected. Only select a
		new one. No she can select no password by choosing blank.
337	Bugfix	Scan2net had problems if the image file to transfer was empty. Now such jobs are
		deleted.

350	Bugfix	The powerdown timer is now saved so it can be shown again on restart.
353	New	Showing more error diagnostics from new scanner models.
	feature	
354	Bugfix	Did not show correct version number for some new scanner models.
356	New	Installation issue solved.
	feature	
357	New	Installation issue solved.
	feature	
358	New	The subscription the scan-to facility is now properly controlled from the check box on the
	feature	scan2net tab.
361	Bugfix	Fixed problem on systems with Italian locale, where the controls on the timer tab showed
		dates and not time of day.
362	Bugfix	Reading the calibration timestamps and validating calibration profiles slightly differently –
		but more correct.

Changes in version 3.3

ID	Note	
231	Bugfix	Now possible to perform B/W mode preview scan in WIA scan wizard.
280	New	Now able to run on systems that have now taskbar running.
	feature	
282	Bugfix	Added missing error message for when remote scanner is reserved by another user.
284	New	You can now install and use remote scanning on networks without DNS running.
	feature	
289	Bugfix	Sometimes the WIA wizard failed to scan.
290	Bugfix	Sometimes the WIA wizard caused scans to be upside-down in the result, even though
		the preview was correctly orientated.
292	New	Combined firmware numbers in a single control on the Info tab.
	feature	
293	New	Energy Star features implemented. Automatic idle time power down controlled on the
	Feature	Timer tab.
294	New	Now show error numbers in the messages window on the Status tab.
	feature	
295	Bugfix	Status polling for remote scanner now works, even if the remote scanner is in boot mode
299	New	Generic scanner ID for more better install process.
	feature	
301	Bugfix	If a remote scanner was installed and no scanner was connected, then a nagging wait
		cursor was shown every 10 seconds.
303	New	Run on Windows 2003 Server. NOTE however, in Win 2003 Server you must configure
	feature	the Windows Acquisition Service to start automatically. Default is that it is not started.
304	New	Now we can determine much faster if a remote scanner is not connected. The timeout for
	feature	the connection can be adjusted through the new IP_TIMEOUT_SECS variable in the new
		[IP] section of the ctx_scan_200.log file
306	New	Now possible to select multiple remote scanners for removal.
	feature	
312	New	Now the add scanner dialog automatically closes if the user has successfully installed a
	feature	scanner manually.

ID	Note	

228	Bugfix	Fixed driver bug that occationally caused applications to report 'unknown handle'
232	Bugfix	WIA image acquisition wizard now no longer says B/W scanners can do color scans
248	Bugfix	USB scanners made more robust to certain command sequence errors.
251	Bugfix	Now handles critical situations around scanner reboots (eg. after leaving standby mode)
		smoothly.
252	Bugfix	Avoiding sending multiple empty files from SCANserver to SCANclient.
256	New	Now old scanners can be accessed over an Ethernet (LAN or WAN) throught the Remote
	feature	Scanning feature.
257	New	Configuration of SCANserver and SCANclient, as well as Remote Scanning configuration
	feature	is gathered in a new Net2Net tab.
258	New	You can install and remove ethernet enabled scanner via the 'selected scanner'
	feature	combobox.
260	New	New and simplified installation procedure.
	feature	
262	Bugfix	Fixed driver failure than could make applications crash on Windows Me system.
268	Change	The SCANclient no longer has it own tray icon. Should be configured via. the Scan2Net
		tab.
272	Change	Now allows 25 scanners installed on one PC.

Changes in version 3.1

ID	Note	
	Change	New layout on the status tab. Replaced error message combo with message window.
231	Bugfix	Preview now possible for B/W mode with WIA wizard on WinXP
240	Bugfix	WS log tab handling older scanner firmware more robust.
243	New	Added Support for scanner consumables (GOLF).
	feature	
249	Bugfix	The driver is made robust, towards scanner reboots when the scanner is use by an
		application. WinXP and Win Me only.

Changes in version 3.0.2

ID	Note	
209	Change	Better format of time fields on info tab.
218	New	If log tab is visible the statistics is updated every 2 seconds.
	feature	
225	Change	New format of 'last calibration timestamp' on the log tab.
226	Bugfix	Roller movement field on the log tab now shown in correct units.
229	New	Added support for new scanner models.
	feature	

Changes in version 3.0.1

ID	Note	
		Multiple languages.
210	Bugfix	Now displays all strings correctly when run by a restricted user

ID	Note	
	New	Introduced the NET Architecture; NET SCANserver and SCANclient

	feature	
	New	Windows Image Acquisition (WIA) support on WinXP and WinME; including the 'Scanners
	feature	and Cameras' scanning wizard
152	New	Added online help through right-click menu and the F1 key
	feature	
144	New	Added error log which can be seen from new Log tab
	feature	
141	New	Introduced service ID field on Info tab
	feature	
126	New	Firmware download is added to Right-click menu->Advanced Options->Update Scanner
	feature	Firmware. This is the recommended way to update Firmware because it prevents
		potential Windows deadlocks!
121	New	Added tab in dialog for preventive maintenance – the Log tab
	feature	
116	New	Now able to control the SCSI adapter settings for optimizing scanner performance under
	feature	STI/WIA
170	Change	Now allows the scanner to be connected to a scsi adapter with id >8
162	Change	Added short-cut to the readme file (this file) in start menu
	Change	Control panel extensions removed from install. All info is available in dialogs.
193	Bug fix	Tool tip on WinMe, WinNT and Win98 when no scanners is connected is now changed to
		"No scanners found. Please connect and install a scanner".
149	Bug fix	Now with automatic support for restricted user under WinXP if SP1 is installed.
143	Bug fix	Scanners with 15 char name length was truncated.

Changes in version 2.1

ID	Note	
	Change	Made one-touch combo's higher, thus leaving room for all apps without scroll.
	Change	Now the one-touch apps are no longer sorted in the combo box because this caused
		wrong behavior on Win98
	Change	Now check for STI apps every time a one-touch button is pressed.
97	Change	Now it's possible to configure one-touch settings, even though no scanner is connected
	Bug fix	Frees some unused memory if no scanner is connected. Possible memory leak.
107	Bug fix	Fixed some strings that were 'hardcoded' in the resourcefile
	Bug fix	Fixed some problems with 4G jumping on and off
94	Bug fix	Fixed bug that made app stop reading status for all scanners if a ACS scanner is
		connected.

ID	Note	
-	New	This application is REQUIRED to run for the one-touch buttons to function.
	feature	
-	New	Easy integrated one-touch button configuration page.
	feature	
-	New	One-touch button functionality now on all OS's and for STI as well as ASPI connectivity
	feature	
83	New	Now pops up if user hits one-touch button and no app is selected.
	feature	
84	New	Added none choice to list of One-touch apps, but kept check-box so that the user can turn
	feature	off event quickly and without forgetting his settings.

71	New	Added serial number on Info tab
	feature	
75	Change	Moved user settings to HKEY_CURRENT_USER
	Bug fix	Fixed some resource strings
74	Bug fix	Now the page remembers changes if user switches back and forth between tabs after
		having changed some selections
73	Bug fix	Now reports scanner timer settings correct in standby mode