

تقرير حالة السيارة

مواصفات السيارة

LJD0AA29XL0088931	7912 GGD	اللوحة	مستعملة	الحالة
2020	السنة	بيجاس	الموديل	الماركة
		بيج	اللون	الممشي
اتوماتيك	القير	ستاندر	المواصفات	LX
بنزين	نوع الوقود	4	عدد السلندرات	حجم المحرك
نعم	اقفال عن بعد	يدوي	مكيف هواء	وسائد هوائية
نعم	تحكم دريكسيون	نعم	نظام ABS	جنوط - طيس
			2	بوصة 14

فحص السيارة

				الحالة الميكانيكية	
OK	نظام الفرامل	OK	حالة ناقل الحركة	OK	حالة الماكينة
OK	العكوس / الدفرانس	OK	نظام التعليق	OK	نظام الكهرباء
				الحالة الداخلية	
OK	الفرش الداخلي	OK	المقاعد	OK	التابلوه والعدادات
				هيكل السيارة	
OK	الايرباج/وسائد الهواء	OK	حالة القوائم	OK	حالة الشاسيه
				الحالة الخارجية	

مقدمة السيارة

- حكة اسفل الصدام، خدوش ونقرات صغيرة بالكبوت والصدام الأمامي.

الجانب الأيمن

- خدوش صغيرة متعددة في الابواب والرفرف الخلفي، نقرات صغيرة في الرفرف والباب الخلفي.
(رش تجميلي بالرفرف الامامي، بدون حوادث مؤثرة على اكياس الهواء، القوائم، الشاسيه او هيكل السيارة الداخلي).

الجانب الايسر

- خدش صغير في المراية الجانبية، نقرات صغيرة في الباب الخلفي.
(رش تجميلي بالرفرف الامامي والخلفي والباب الامامي، بدون حوادث مؤثرة على اكياس الهواء، القوائم، الشاسيه او هيكل السيارة الداخلي).

خلفية السيارة

- خدوش صغيرة متفرقة في الصدام.
(رش تجميلي بالصدام الخلفي، بدون حوادث مؤثرة على اكياس الهواء، القوائم، الشاسيه او هيكل السيارة الداخلي).

CONDITION REPORT

Vehicle Information

LJD0AA29XL0088931		7912 GGD	PLATE	USED CAR	STATUS
2020	YEAR	PEGAS	MODEL	KIA	MAKE
		Beige	COLOR	88762	Odometer
AUTOMATIC	TRANSMISSION	STD	SPECS	LX	GRADE
PETROL	FUEL	4	CYLINERS	1.4 L	ENGINE
YES	Centerlock	MANUAL	A/C	2	AIRBAG
YES	STEERING CNTR	YES	ABS	14"	Wheel caps

Vehicle Inspection

				Mechanical Condition	
OK	BRAKES / ABS	OK	TRANSMISSION	OK	ENGINE
OK	AXLES / Diffrenc.	OK	Suspension sys.	OK	Electricity sys.
				Interior Condition	
OK	FLOORMAT	OK	SEATS	OK	DASHBOARD
				CHASSIS / UNIBODY	
OK	AIRBAG	OK	PILLARS	OK	CHASSIS
				Exterior Condition	

Front Portion

- Long scratch under bumper and small multi scratches on the bumper and hood.

Right Portion

- Multi small scratches on the front and rear doors and rear fender.

(Cosmetic painting on the front fender, without any damages of vehicle's airbags, pillars, chassis, exterior or interior unibody)

Left Portion

- Small scratches on rear door.

(Cosmetic painting on the front door, front and rear fenders, without any damages of vehicle's airbags, pillars, chassis, exterior or interior unibody)

Rear Portion

- Light Scratches on rear bumper and trunk door.

(Cosmetic painting on the rear bumper, without any damages of vehicle's airbags, pillars, chassis, exterior or interior unibody).