

التفاصيل والمواصفات					
تفاصيل السيارة					
الحالة	مستعملة	اللوحة	2407 JGD	KL1CD6CA0LC404533	
الماركة	شيفروليه	الموديل	سبارك	السنة	2020
الممشي	91230	اللون	ابيض		
الفئة	LS	المواصفات	ستاندر	القير	اتوماتيك
حجم المحرك	لتر 1.4	عدد السلندرات	4	نوع الوقود	بنزين
المواصفات					
وسائد هوائية	2	مكيف هواء	يدوي	اقفال عن بعد	نعم
جنوط - طيس	بوصة 14	نظام ABS	نعم	تحكم دريكسيون	نعم
الحالة الميكانيكية					
حالة الماكينة	OK	حالة ناقل الحركة	OK	نظام الفرامل	OK
نظام الكهرباء	OK	نظام التعليق	OK	العكوس / الدفرانس	OK
الحالة الداخلية					
التابلوه والعدادات	1	المقاعد	OK	الفرش الداخلي	OK
خدش صغير جانب منفذ الUSB					
هيكل السيارة					
الشاسيه الامامي	OK	الشاسيه الخلفي	OK	الايرباج/وسائد الهواء	OK
القوائم	OK				
الحالة الخارجية					

السيارة

ش متفرقة بالصدام الامامي، والكبوت، طعجة صغيرة في مقدمة الكبوت.

ب الأيمن

ش صغيرة متفرقة في الباب الامامي.
تجميلي للرفرف الامامي والباب الامامي والخلفي بدون حوادث مؤثرة على الهيكل أو الاجزاء الخارجية أو الداخلية للسيارة)

ب الايسر

وش على الباب الخلفي.
تجميلي للرفرف الخلفي والباب الامامي بدون حوادث مؤثرة على الهيكل أو الاجزاء الخارجية أو الداخلية للسيارة)

السيارة

Vehicle Information					
				Vehicle Details	
KL1CD6CA0LC404533		2407 JGD	PLATE	USED CAR	STATUS
2020	YEAR	Spark	MODEL	Chevrolet	MAKE
		WHITE	COLOR	91230	Odometer
AUTOMATIC	TRANSMISSION	STD	SPECS	LS	GRADE
PETROL	FUEL	4	CYLINERS	1.4 L	ENGINE
				Specifications	
YES	Centerlock	MANUAL	A/C	2	AIRBAG
YES	STEERING CNTR	YES	ABS	14"	Wheel caps
Condition Report					
				MECHANICAL STATUS	
OK	BRAKES / ABS	OK	TRANSMISSION	OK	ENGINE
OK	AXLES / Diffr.	OK	Suspension sys.	OK	Electricity sys.
				Interior Status	
OK	FLOORMAT	OK	SEATS	OK	DASHBOARD
				CHASSIS / UNIBODY	
OK	AIRBAG	OK	PILLARS	OK	CHASSIS
				EXTERIOR STATUS	

Front Portion

- Multi scratches on the front bumper and hood, one dent on the hood front.

Right Portion

- Small scratches on the front fender, front & rear doors, one dent on the front door.

(Cosmetic painting on front fender, front and rear doors, without any damages of chassis, pillars, exterior or interior parts)

Left Portion

- Small scratches on rear door.

(Cosmetic painting on front door and rear fender, without any damages of chassis, pillars, exterior or interior parts)

Rear Portion

- Small Scratches on trunk door .