

تقرير حالة السيارة

مواصفات السيارة

MDHBN7AD7LG698798	6313 AKD	اللوحة	مستعملة	الحالة
2020	صني	الموديل	نيسان	الماركة
السنة	أبيض	اللون	96677	الممشي
اتوماتيك	القير	ستاندر	SV	الفئة
بنزين	نوع الوقود	عدد السلندرات	1.5 لتر	حجم المحرك
نعم	اقفال عن بعد	يدوي	2	وسائد هوائية
نعم	تحكم دريكسيون	نظام ABS	بوصة 14	جنوط - طيس

فحص السيارة

الحالة الميكانيكية			
جيدة	حالة ناقل الحركة	جيدة	حالة الماكينة
جيدة	نظام التعليق	جيدة	نظام الكهرباء
جيدة	نظام الفرامل	جيدة	حالة الماكينة
جيدة	العكوس / الدفرانس	جيدة	نظام الكهرباء
الحالة الداخلية			
جيدة	المقاعد	جيدة	التابلوه والعدادات
-			
هيكل السيارة			
جيدة	حالة القوائم	جيدة	حالة الشاسيه
جيدة	الايرباج/وسائد الهواء	جيدة	حالة الشاسيه
الحالة الخارجية			

مقدمة السيارة

- خدوش صغيرة بالكبوت.
(رش تجميلي بالصدام الامامي، بدون حوادث مؤثرة على الايرباج، القوائم، الشاسيه والهيكل الداخلي أو الخارجي)

الجانب الأيمن

- خدش صغير بالرפרف الامامي وخدش بالرפרف الخلفي، خدوش صغيرة بالابواب.

الجانب الايسر

- خدوش صغيرة بالرפרف الأمامي والباب الامامي والخلفي.

خلفية السيارة

- خدوش صغيرة بالصدام الخلفي.
(رش تجميلي بالصدام الامامي، بدون حوادث مؤثرة على الايرباج، القوائم، الشاسيه والهيكل الداخلي أو الخارجي)

CONDITION REPORT

Vehicle Information

MDHBN7AD7LG698798		6313 AKD	PLATE	USED CAR	STATUS
2020	YEAR	SUNNY	MODEL	NISSAN	MAKE
		WHITE	COLOR	96677	Odometer
AUTOMATIC	TRANSMISSION	STD	SPECS	SV	GRADE
PETROL	FUEL	4	CYLINERS	1.5 L	ENGINE
YES	Centerlock	MANUAL	A/C	2	AIRBAG
YES	STEERING CNTR	YES	ABS	14"	Wheel Caps

Vehicle Inspection

				Mechanical Condition	
Good	BRAKES / ABS	Good	TRANSMISSION	Good	ENGINE
Good	AXLES / Diffr.	Good	Suspension sys.	Good	Electricity sys.
				Interior Condition	
Good	FLOORMAT	Good	SEATS	Good	DASHBOARD
				CHASSIS / UNIBODY	
Good	AIRBAG	Good	PILLARS	Good	CHASSIS
				Exterior Condition	

Front Portion

- Light scratch on the hood.

(Cosmetic painting on the front bumper, without any damages of vehicle's airbags, pillars, chassis, exterior or interior unibody)

Right Portion

- Small Scratch on the front fender, and Rear fender, multi scratches on front and rear doors.

Left Portion

- Multi scratches on rear fender, front and rear doors and light scratch on the front fender.

Rear Portion

- Light Scratches on rear bumper.

(Cosmetic painting on the hood, without any damages of vehicle's airbags, pillars, chassis, exterior or interior unibody)