

تقرير حالة السيارة

مواصفات السيارة

MDHBN7AD7KG662589	8155 RTD	اللوحة	مستعملة	الحالة
2019	صني	الموديل	نيسان	الماركة
السنة	أبيض	اللون	54069	الممشي
اتوماتيك	القير	ستاندر	SV	الفئة
بنزين	نوع الوقود	عدد السلندرات	1.5 لتر	حجم المحرك
نعم	اقفال عن بعد	يدوي	2	وسائد هوائية
نعم	تحكم دريكسيون	نعم	14 بوصة	جنوط - طيس
		نظام ABS		

فحص السيارة

				الحالة الميكانيكية	
جيدة	نظام الفرامل	جيدة	حالة ناقل الحركة	جيدة	حالة الماكينة
جيدة	العكوس / الدفرانس	جيدة	نظام التعليق	جيدة	نظام الكهرباء
				الحالة الداخلية	
جيدة	الفرش الداخلي	جيدة	المقاعد	جيدة	التابلوه والعدادات
-					
				هيكل السيارة	
جيدة	الايبراج/وسائد الهواء	جيدة	حالة القوائم	جيدة	حالة الشاسيه
				الحالة الخارجية	

مقدمة السيارة

- خدوش صغيرة متفرقة بالصدام الامامي والكبوت.

الجانب الأيمن

- خدش صغير بالرفرف الامامي - خدوش متفرقة بالباب الامامي والخلفي والرفرف الخلفي.

الجانب الايسر

- خدوش صغيرة بالباب الامامي وغطاء المراية الجانبية.

خلفية السيارة

- خدش صغير بالصدام الخلفي.

(رئش تجميل بالصدام الخلفي وبالشنطة، بدون حوادث مؤثرة على الايرياج، القوائم، الشاسيه والهيكل الداخلي أو الخارجي)

CONDITION REPORT

Vehicle Information

MDHBN7AD7KG662589		8155 RTD	PLATE	USED CAR	STATUS
2019	YEAR	SUNNY	MODEL	NISSAN	MAKE
		WHITE	COLOR	54069	Odometer
AUTOMATIC	TRANSMISSION	STD	SPECS	SV	GRADE
PETROL	FUEL	4	CYLINERS	1.5 L	ENGINE
YES	Centerlock	MANUAL	A/C	2	AIRBAG
YES	STEERING CNTR	YES	ABS	14"	Wheel Caps

Vehicle Inspection

				Mechanical Condition	
Good	BRAKES / ABS	Good	TRANSMISSION	Good	ENGINE
Good	AXLES / Diffr.	Good	Suspension sys.	Good	Electricity sys.
				Interior Condition	
Good	FLOORMAT	Good	SEATS	Good	DASHBOARD
				CHASSIS / UNIBODY	
Good	AIRBAG	Good	PILLARS	Good	CHASSIS
				Exterior Condition	

Front Portion

- Light scratch on the front bumper and hood.

(Cosmetic painting on the front bumper, without any damages of vehicle's airbags, pillars, chassis, exterior or interior unibody)

Right Portion

- Small Scratch on the front fender, multi scratches on front and rear doors, small dent on the rear fender.

Left Portion

- Small scratches on the front and left mirror cover.

Rear Portion

- Light Scratches on the rear bumper.

(Cosmetic painting on rear bumper and trunk door, without any damages of vehicle's airbags, pillars, chassis, exterior or interior unibody)