

التفاصيل والمواصفات					
تفاصيل السيارة					
الحالة	مستعملة	اللوحة	6331 AKD	MDHBN7AD4LG696460	
الماركة	نيسان	الموديل	صني	السنة	2020
الممشتي	104197	اللون	فضي		
اتوماتيك	الفئة	المواصفات	ستاندر	القياس	
بنزين	حجم المحرك	عدد السلندرات	4	نوع الوقود	
المواصفات					
نعم	وسائد هوائية	مكيف هواء	يدوي	اقفال عن بعد	
نعم	جنوط - طيس	نظام ABS	نعم	تحكم دريكسيون	
الحالة الفنية					
الحالة الميكانيكية					
OK	حالة الماكينة	OK	حالة ناقل الحركة	نظام الفرامل	OK
OK	نظام الكهرباء	OK	نظام التعليق	العكوس / الدفرانس	OK
الحالة الداخلية					
OK	التابلوه والعدادات	OK	المقاعد	الفرش الداخلي	OK
هيكل السيارة					
OK	القوائم	OK	الشاسيه الخلفي	الابراج/وسائد الهواء	OK
الحالة الخارجية					

قدمة السيارة (1 ملاحظة)
خدوش متفرقة بالصدام الامامي والكبوت

جانب الأيمن (4 ملاحظات)
خدوش خفيفة متفرقة في الرفرف الامامي ، الباب الامامي والخلفي، والرفرف الخلفي ، طعجة صغيرة على الرفرف الخلفي
رش تجميلي للرفرف الخلفي بدون حوادث مؤثرة على الهيكل او الأجزاء الخارجية أو الداخلية للسيارة)

جانب الابر (2 ملاحظات)
خدوش خفيفة متفرقة في الرفرف الامامي ، الباب الامامي والخلفي، والرفرف الخلفي ، طعجة صغيرة على الرفرف الخلفي
رش تجميلي للرفرف الخلفي بدون حوادث مؤثرة على الهيكل او الأجزاء الخارجية أو الداخلية للسيارة)

لفية السيارة (1 ملاحظات)
- خدش صغير بالصدام الخلفي

Vechicle Information									
						Vehicle Details			
MDHBN7AD4LG696460		6331 AKD		PLATE		USED CAR		STATUS	
2020		YEAR		SUNNY		MODEL		NISSAN	
		silver		COLOR		104197		Odometer	
AUTOMATIC		TRANSMISSION		Std		SPECS		SV	
PETROL		FUEL		4		CYLINERS		1.5 L	
						Specifications			
YES		Centerlock		MANUAL		A/C		2	
YES		STEERING CNTR		YES		ABS		14"	
Condition Report									
						MECHANICAL STATUS			
OK		BRAKES / ABS		OK		TRANSMISSION		OK	
OK		AXLES / Diffr.		OK		Suspension sys.		OK	
						Interior Status			
OK		FLOORMAT		OK		SEATS		OK	
						CHASSIS / UNIBODY			
OK		AIRBAG		OK		PILLARS		OK	
						EXTERIOR STATUS			
Front Portion (1 Remark) - Multi scratches on the front bumper and Hood. Right Portion (4 Remarks) - Small scratchs on front fender, front and rear doors, and rear fender, small dent on the rear fender. (Cosmetic painting on rear fender, without any damages of chassis, pillars, exterior or interior parts) Left Portion (2 Remarks) - Small scratchs on front fender, front and rear doors, and rear fender. (Cosmetic painting on rear fender, without any damages of chassis, pillars, exterior or interior parts) Rear Portion (2 Remarks) - Light Scratche on rear bumper (Cosmetic painting on trunk door, without any damages of chassis, pillars, exterior or interior parts)									